



PHOTO 1: THE LEAKING PACKING AS BEEN FIXED AND MAINTENANCE HAS BEEN PERFORMED TO OPERATING EQUIPMENT. THE SPILL WAS CONTROLLED IMMEDIATELY UPON CONTACT FROM COGCC INSPECTOR. ALL STANDING LIQUIDS AND CONTAMINATED SOILS WERE REMOVED FROM LOCATION AND PROPERLY DISPOSED OF. THE SELF INSPECTION PROCESS HAS BEEN REVIEWED.