

# OIL AND GAS CONSERVATION DEPARTMENT OF NATURAL RESOURCES OF THE STATE OF COLORADO

File in duplicate for Patented and Federal lands.  
File in triplicate for State lands.



RECEIVED

AUG 15 1983

## SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER		5. LEASE DESIGNATION AND SERIAL NO. CV Cogburn of Utah
2. NAME OF OPERATOR ANR Production Company		6. INDIAN, ALLOTTEE OR TRIBE NAME N/A
3. ADDRESS OF OPERATOR 717 17th Street - Suite 2500, Denver, Colorado 80202		7. UNIT AGREEMENT NAME N/A
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface 1320' FNL & 1320' FEL		8. FARM OR LEASE NAME Cogburn Weco
At proposed prod. zone Same		9. WELL NO. 1-6
14. PERMIT NO. 76-587		10. FIELD AND POOL, OR WILDCAT Playa Field Walsh
15. ELEVATIONS (Show whether DF, RT, GR, etc.) 3969' GR		11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec 6, T33S, R43W
		12. COUNTY Baca
		13. STATE Colorado

16.

### Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

#### NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON

CHANGE PLANS

#### SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

Date of work 8/4/83

- A. RU plugging service. Pmpd 10 sxs C1 G cmt followed by 1 sx cottonseed hulls followed w/20 sxs C1 G cmt.
- B. Fill 4-1/2" csg to 1500' w/prod wtr. Pmpd 1 sx cottonseed hulls followed w/30 sxs C1 G cmt to surf. Tst to 1000 psi. OK.
- C. Cut 4-1/2" & 8-5/8" csg 4' below GL. Weld individual 1/2" steel plate 360° on cut-offs. P&A, 7 pm, 8/4/83.

EXHAUSTED  
GAS WELL

VAR	
UP	
MM	
JAM	
ROC	
LAR	
GCM	

18. I hereby certify that the foregoing is true and correct

SIGNED

L. P. Streeb

TITLE District Production Supt.

DATE

8-11-83

(This space for Federal or State office use)

APPROVED BY

William Smith

TITLE

O &amp; G Cons. Comm.

DATE

AUG 24 1983

CONDITIONS OF APPROVAL, IF ANY:

7 E

✓

2