

State of Colorado  
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:  
403470551

Date Received:  
07/20/2023

FIR RESOLUTION FORM

Overall Status: FRQ

CA Summary:

1 of 6 CAs from the FIR responded to on this Form

0 CA Completed  
1 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10433

Name of Operator: LARAMIE ENERGY LLC

Address: 1700 LINCOLN ST STE 3950

City: DENVER State: CO Zip: 80203

Contact Name and Telephone:

Name: \_\_\_\_\_

Phone: ( ) \_\_\_\_\_ Fax: ( ) \_\_\_\_\_

Email: \_\_\_\_\_

Additional Operator Contact:

Contact Name	Phone	Email
<u>Arauz, Steven</u>		<u>steven.arauza@state.co.us</u>
<u>.Laramie</u>		<u>cogccnotifications@laramie-energy.com</u>

COGCC INSPECTION SUMMARY:

FIR Document Number: 696205102

Inspection Date: 07/14/2023

FIR Submit Date: 07/18/2023

FIR Status: \_\_\_\_\_

Inspected Operator Information:

Company Name: LARAMIE ENERGY LLC

Company Number: 10433

Address: 1700 LINCOLN ST STE 3950

City: DENVER State: CO Zip: 80203

LOCATION - Location ID: 452807

Location Name: CC Number: 0697-03-07 County: \_\_\_\_\_  
Pad

Qtrqtr: Lot 11 Sec: 3 Twp: 6S Range: 97W Meridian: 6

Latitude: 39.558439 Longitude: -108.205081

FACILITY - API Number: 05-045- -00 Facility ID: 452807

Facility Name: CC Number: 0697-03-07  
Pad

Qtrqtr: Lot 11 Sec: 3 Twp: 6S Range: 97W Meridian: 6

Latitude: 39.558439 Longitude: -108.205081

CORRECTIVE ACTIONS:

6  CA# 175772

Corrective Action: Comply with Rule 1002.f. The "Date of Discovery" is being used as the corrective action date; Location will remain out of compliance until corrective action has been resolved.

Date: \_\_\_\_\_

Response: FACTUAL REVIEW REQUEST

Basis for Review: Equipment is not owned or controlled by the operator

Operator Comment: The self-contained porta johns are secured and maintained by a 3rd party contractor. The units are located within the pad boundaries and within the bermed secondary containment for the pad. The installation of a secondary containment would create a tripping hazard.

COGCC Decision: **Not Approved**

COGCC Representative: The porta-john units observed on Location have not been properly secured to prevent a spill, or lacked control measures at the units to adequately contain a spill if one were to occur; this is an improper waste management practice and does not comport with ECMC requirements.

Additionally, Laramie remains responsible for oversight and management of their Location, regardless of ownership of equipment, materials, etc... that may exist on Laramie's location(s).

COGCC Supervisor: The porta-john units observed on Location have not been properly secured to prevent a spill, or lacked control measures at the units to adequately contain a spill if one were to occur; this is an improper waste management practice and does not comport with ECMC requirements.

Additionally, Laramie remains responsible for oversight and management of their Location, regardless of ownership of equipment, materials, etc... that may exist on Laramie's location(s).

**OPERATOR COMMENT AND SUBMITTAL**

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Lori Muhr

Signed: \_\_\_\_\_

Title: Regulatory Specialist

Date: 7/20/2023 7:48:04 AM

**ATTACHMENT LIST**

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
403470551	FIR RESOLUTION SUBMITTED

Total Attach: 1 Files