

Inspection Photos

API: 071-08761

Operator: EVERGREEN NATURAL RESOURCES

Inspection Date: 7/20/2023



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08761 | Date: 7/20/2023

Inspection Photos



Photo 1. Facing west at the beginning of the access road. The willows along the road side have died from what appears to be incorrectly applied herbicide treatment.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08761 | Date: 7/20/2023

Inspection Photos



Photo 2. The dead willow along this area need to be cut and removed.



Inspection Photos



Photo 3. Facing back at the willows along the access road that appear to have been sprayed from recent weed treatment. Did not observe any other dying vegetation beyond the road side area.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08761 | Date: 7/20/2023

Inspection Photos



Photo 4. Facing west along the access road. Undesirable weeds along the road are wilted from weed control.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08761 | Date: 7/20/2023

Inspection Photos



Photo 5. Facing south toward the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08761 | Date: 7/20/2023

Inspection Photos



Photo 6. Facing southeast along the fill slope which is stabilized with perennial vegetation.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08761 | Date: 7/20/2023

Inspection Photos



Photo 7. Well sign posted at meter shed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08761 | Date: 7/20/2023

Inspection Photos



Photo 8. Facing toward the wellsite.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08761 | Date: 7/20/2023

Inspection Photos



Photo 9. The fence around the pit is in disrepair.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08761 | Date: 7/20/2023

Inspection Photos



Photo 10. There is oily fluid in the engine skid that needs to be cleaned up.

