

TEP
KP 32-17
Location # 335239



Well heads



Tank battery



TEP
KP 32-17
Location # 335239



Fresh water tanks



Separators and Meter calibration card not conspicuously posted.



TEP
KP 32-17
Location # 335239



Well signage is faded and illegible



Open line on tanks

TEP
KP 32-17
Location # 335239



Waddles failing from previous inspection and lack of stabilization/ erosion



Waddles failing from recent inspection and lack of stabilization/ erosion

TEP
KP 32-17
Location # 335239



Erosion blanket from previous inspection and lack of stabilization.



Erosion blanket from recent inspection and lack of stabilization.



TEP
KP 32-17
Location # 335239



Waddles failing from recent inspection



Waddles failing from recent inspection

TEP
KP 32-17
Location # 335239



Waddles failing from previous inspection



Waddles failing from recent inspection and erosion