

<b>NON-HAZARDOUS WASTE MANIFEST</b>		Generator's EPA ID No.	EEL00141	Page 1 of 1	<b>PAWNEE WASTE LLC</b>	
G e n e r a t o r	Generator's Name and Mailing Address <b>Bohler Well Service LLC 2116 US HWY 6 Sterling, CO 80751</b>			Manifest # <b>95,129</b>		
	Generator's Phone (including area code)					
	Transporter Company Name <b>Bohler</b>	US EPA ID No.2	Transporter's Phone			
	Designated Facility Name and Site Address <b>Pawnee Waste 47368 County Rd 118 Grover, CO 80729</b>	Weld County USR No. <b>USR15-0048</b>	Facility Phone <b>(970) 889-0006</b>			
	Well Location/Rig/Waste Location <b>I.G.S. Behring #1</b>		Haul Container <b>S-31</b>	Total Quantity <b>25.22</b>	UNIT/WT <b>bbls</b>	
	Waste Type (i.e. Cuttings, Pit material, spill cleanup) <b>Tank bottom (sludge)</b>					
	Special Handling Instructions					
Generator's Certification: I certify the materials described above on this manifest are not subject to federal regulations for reporting proper disposal of Hazardous Waste						
Printed/Typed Name <b>1</b>		Signature			Date:	
T r a n s p o r t e r	Transporter Acknowledgement of Receipt of Materials					
	Printed/Typed Name <b>Charlie Myers</b>		Signature <b>Charlie Myers</b>			Date: <b>6/28/2023</b>
F a c i l i t y	Discrepancy Indication Space					
	Facility Owner or Operator: Certification of receipt of waste materials covered by this manifest except as noted above					
	Printed/Typed Name <b>D. Norris</b>		Signature <b>D. Norris</b>			Date: <b>6-28-23</b>

IN: 6pm  
out: 10:50pm