

State of Colorado  
Energy & Carbon Management Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

403466621

Date Received:

07/17/2023

## FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

3 of 3 CAs from the FIR responded to on this Form

3 CA Completed  
0 Factual Review Request

### OPERATOR INFORMATION

OGCC Operator Number: 46290

Name of Operator: KP KAUFFMAN COMPANY INC

Address: 1700 LINCOLN ST STE 4550

City: DENVER State: CO Zip: 80203

Contact Name and Telephone:

Name: \_\_\_\_\_

Phone: ( ) \_\_\_\_\_ Fax: ( ) \_\_\_\_\_

Email: \_\_\_\_\_

Additional Operator Contact:

Contact Name

Victoria Dizghinjili

Phone

303-825-4822

Email

vdizghinjili@kpk.com

### COGCC INSPECTION SUMMARY:

FIR Document Number: 699106918

Inspection Date: 07/12/2023

FIR Submit Date: 07/12/2023

FIR Status: \_\_\_\_\_

### Inspected Operator Information:

Company Name: KP KAUFFMAN COMPANY INC

Company Number: 46290

Address: 1700 LINCOLN ST STE 4550

City: DENVER State: CO Zip: 80203

### LOCATION - Location ID: 330672

Location Name: HSR-LOST CREEK-63N62W Number: 29SESE County: \_\_\_\_\_

Qtrqr: SESE Sec: 29 Twp: 3N Range: 62W Meridian: 6

Latitude: 40.190789 Longitude: -104.341516

### FACILITY - API Number: 05-123-00 Facility ID: 330672

Facility Name: HSR-LOST CREEK-63N62W Number: 29SESE

Qtrqr: SESE Sec: 29 Twp: 3N Range: 62W Meridian: 6

Latitude: 40.190789 Longitude: -104.341516

### CORRECTIVE ACTIONS:

1 ☒ CA# 175237

Corrective Action: Repair or install berms or other secondary containment devices per Rule 603.o.

Date: 07/21/2023

Response: CA COMPLETED

Date of Completion: 07/17/2023

Operator Comment: Berms have been repaired. Please see attached picture.

COGCC Decision: Approved via an AMI

COGCC  
Representative:

2 ☒ CA# 175238

Corrective Action: Install sign to comply with Rule 605.g.

Date: 07/21/2023

Response: CA COMPLETED

Date of Completion: 07/17/2023

Operator  
Comment:

Capacity label for the crude oil tank has been installed. Please see attached picture.

COGCC Decision: Approved via an AMI

COGCC  
Representative:

3 ☒ CA# 175239

Corrective Action: "Properly dispose of oily waste in accordance with 905.e."

Date: 07/21/2023

Response: CA COMPLETED

Date of Completion: 07/17/2023

Operator  
Comment:

Stained soil on west side of production tanks outside of berm has been removed.

COGCC Decision: Approved via an AMI

COGCC  
Representative:

#### OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Victoria Dizghinjili

Signed:

Title: Engineering Tech

Date: 7/17/2023 1:21:23 PM

### ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
403466621	FIR RESOLUTION SUBMITTED
403466700	Berms repaired, stained soil removed PIC1
403466705	Tank and riser labeled PIC2

Total Attach: 3 Files