

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

08/03/2023

Submitted Date:

08/03/2023

Document Number:

699107062

FIELD INSPECTION FORM

Loc ID 317961 Inspector Name: Burns, Adam On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 100322
 Name of Operator: NOBLE ENERGY INC
 Address: 2001 16TH STREET SUITE 900
 City: DENVER State: CO Zip: 80202

Findings:

- 4 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
,		rbucogccinspectionreports@chevron.onmicrosoft.com	All Inspections

General Comment:

[Routine Inspection](#)

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

Type WELLHEAD

Comment: [panel fence laying on the ground needs to be put back together. See attached photo](#)

Corrective Action: [Comply with the fencing requirements per the 1002a rules](#)

Date: 08/25/2023

Venting:

Yes/No NO

Comment:

Corrective Action:

Date:

Flaring:

Type		
Comment:	<input type="text"/>	
Corrective Action:	<input type="text"/>	Date: <input type="text"/>

COGCC Comments

Comment	User	Date
<p>ECMC Inspection Report Summary On Wednesday 8/2/23 at approximately 1013hrs I, Inspector Adam Burns, Conducted an on-site inspection at Lyle V. Cooksey Gas Unit 1 of Chevron. API # 05-123-08045 in Weld County, Colorado. During this inspection the following possible compliance issues were observed: panel fence laying on the ground needs to be put back together. Comply with the fencing requirements per the 1002a rules. With a Corrective Action date of 8/25/23 A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with ECMC rules. This is a summary of the inspection report.</p>	burnsa	08/03/2023

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699107063	Inspection Photo	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6205728