

State of Colorado
Energy & Carbon Management Commission



1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Document Number:

403486436

Date Received:

08/03/2023

FIR RESOLUTION FORM

Overall Status:

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10773

Name of Operator: FUNDARE RESOURCES OPERATING COMPANY LLC

Address: 5251 DTC PKWY STE 950

City: GREENWOOD VILLAGE State: CO Zip: 80111

Contact Name and Telephone:

Name: _____

Phone: () Fax: ()

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

Parrish, Melissa

970-397-3896

mparrish@fundareresources.com

Smith, Sydney

303-910-4511

ssmith@fundareresources.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 708200219

Inspection Date: 05/03/2023

FIR Submit Date: 05/08/2023

FIR Status: _____

Inspected Operator Information:

Company Name: FUNDARE RESOURCES OPERATING COMPANY LLC

Company Number: 10773

Address: 5251 DTC PKWY STE 950

City: GREENWOOD VILLAGE State: CO Zip: 80111

LOCATION - Location ID: 430314

Location Name: Razor Number: 30K Pad County: _____

Qtrqr: NESW Sec: 30 Twp: 10N Range: 58W Meridian: 6

Latitude: 40.808419 Longitude: -103.910528

FACILITY - API Number: 05-123-00 Facility ID: 430314

Facility Name: Razor Number: 30K Pad

Qtrqr: NESW Sec: 30 Twp: 10N Range: 58W Meridian: 6

Latitude: 40.808419 Longitude: -103.910528

CORRECTIVE ACTIONS:

1 CA# 170649

Corrective Action: Perform reclamation in accordance with Rule 1003. Establish vegetation with total perennial, non-invasive uniform plant cover of at least eighty (80) percent of reference area levels. Use a seed mixture requested by the surface owner, or a mixture prescribed by the local county NRCS. Ensure erosion controls are implemented to stabilize the seeded soil, and continue to monitor and manage this site until the location meets Rule 1003 standards. Corrective action date is the date the location was observed out of compliance.

Date: 05/03/2023

Response: CA COMPLETED

Date of Completion: 05/03/2023

Operator Comment: To Address Rule 1003 In Regards to the Reclamation & Management of the Noxious Weeds is Being Addressed & Implemented Under Our Weed Management Plan for 2023.

COGCC Decision: _____

COGCC Representative: _____

2 CA# 170650

Corrective Action: Immediately install or repair required BMPs per Rule 1002.f. in accordance with good engineering practices. Corrective action date is the date the location was observed out of compliance, as the location should be in compliance at all times.

Date: 05/03/2023

Response: CA COMPLETED

Date of Completion: 05/03/2023

Operator Comment: The Cut Slope on Location Has Been Redefined With Reclamation Efforts Implemented To Help Prevent Erosion During Stormwater Events. BMPs of Straw Blankets Have Been Installed In Accordance With Rule 1002.f. - Please See Photo Documentation.

COGCC Decision: _____

COGCC Representative: _____

OPERATOR COMMENT AND SUBMITTAL

Comment: _____

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Melissa Parrish

Signed: _____

Title: Production Regulatory Com

Date: 8/3/2023 7:31:59 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
------------------------	--------------------

403486437	Razor Federal 30K Completed COGCC Corrective Actions
-----------	--

Total Attach: 1 Files