

Weld OEM Spill Report Form

Submitted on	7 August 2023, 8:48AM
Receipt number	1248
Related form version	17

Company

Company name	Civitas Resources
Address	650 Southgate Drive
City	Windsor
State	Colorado
Zip code	80550

Contact Information

Contact person	Costin McQueen
Contact phone	720-384-6452
Contact email	cmcqueen@civiresources.com

About the Spill

Date incident occurred	08/05/2023
Was 9-1-1 called for this incident	No
Longitude	-104.579931
Latitude	40.077778
Fire department/district	Hudson Fire
Where did the incident occur?	Oil and gas facility/pipeline

Oil and Gas Incident

Well site name	Grinde 1-64-5_4 SWNW
----------------	----------------------

Section	5
Township	1N
Range	64W
Where did the spill occur	Tank battery
Have you submitted a form 19	Yes
Form 19 report number	403487711

Product Spilled

Product spilled	oil, produced water
Number of barrels spilled	4
Emergency precautions taken	N/A
Extremely hazardous substance	No
Acute or chronic health risks	No
Did the spill affect or end near a waterway, irrigation ditch, or a retention pond?	No
What caused the spill/release?	Equipment failure

Narrative

<p>Include specific incident information and mitigation actions taken to stop and clean-up the spill/release</p>	<p>A compromised gasket on the Grinde 1-64-5-0108C separator resulted in fluid to be spilled to the ground surface. All spilled fluid remained on pad. The impacted soil will be removed and hauled for disposal. Confirmation soil samples will be collected in compliance with ECMC Table 915-1.</p>
<p>Acknowledgement</p>	<p>I acknowledge that a written follow-up notice must be submitted to Weld County OEM/LEPC as soon as practicable after the release. The follow-up notice must update information included in the initial notice and provide information on actual response actions taken and advice regarding medical attention necessary for citizens exposed.</p>