

FORM
6Rev
11/20

State of Colorado

Energy & Carbon Management Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894-2109



DE	ET	OE	ES
----	----	----	----

Replug By Other Operator

Document Number:

403479219

Date Received:

WELL ABANDONMENT REPORT

This form is to be submitted as an Intent to Abandon whenever an abandonment is planned on a borehole. After the abandonment is complete, this form shall again be submitted as a Subsequent Report of the actual work completed. The approved intent shall be valid for six months after the approval date, after that period, a new intent will be required. Attachments required with the Intent to Abandon are wellbore diagrams of the current configuration and the proposed configuration with plugs set.

A Subsequent Report of Abandonment shall indicate the actual work completed. Attachments required with a Subsequent Report are a wellbore diagram showing plugs that were set and casing remaining in the hole, the job summaries from all plugging contractors used, including wireline and cementing (third party verification) and any logs that may have been run during abandonment.

OGCC Operator Number: 69175

Contact Name: Valerie Danson

Name of Operator: PDC ENERGY INC

Phone: (970) 506-9272

Address: 1099 18TH STREET SUITE 1500

Fax:

City: DENVER

State: CO

Zip: 80202

Email: valerie.danson@pdce.com

For "Intent" 24 hour notice required,

Name:

Tel:

COGCC contact:

Email:

Type of Well Abandonment Report: ☐ Notice of Intent to Abandon ☒ Subsequent Report of Abandonment

API Number 05-123-08111-00

Well Name: EASTMAN KODAK

Well Number: 1

Location: QtrQtr: SESW

Section: 27

Township: 6N

Range: 67W

Meridian: 6

County: WELD

Federal, Indian or State Lease Number:

Field Name: WILDCAT

Field Number: 99999

Only Complete the Following Background Information for Intent to Abandon

Latitude: 40.451950

Longitude: -104.882080

GPS Data: GPS Quality Value: 1.1 Type of GPS Quality Value: PDOP Date of Measurement: 04/13/2023

Reason for Abandonment: ☐ Dry ☐ Production Sub-economic ☐ Mechanical Problems☐ OtherCasing to be pulled: ☐ Yes ☐ No

Estimated Depth:

Fish in Hole: ☐ Yes ☐ No

If yes, explain details below

Wellbore has Uncemented Casing leaks: ☐ Yes ☐ No

If yes, explain details below

Details:

Current and Previously Abandoned Zones

Formation	Perf. Top	Perf. Btm	Abandoned Date	Method of Isolation	Plug Depth
J SAND	7572	7600	12/30/1974	CEMENT	7340

Total: 1 zone(s)

Casing History

Casing Type	Size of Hole	Size of Casing	Grade	Wt/Ft	Csg/Liner Top	Setting Depth	Sacks Cmt	Cmt Btm	Cmt Top	Status
SURF	12+1/4	8+5/8	J55	24	0	262	250	262	0	VISU
1ST	7+7/8	5+1/2	J55	15.5	0	7685	270	7685	6750	CALC
S.C. 1.1						4200	335	4200	3010	CALC

Plugging Procedure for Intent and Subsequent Report

CIBP #1: Depth _____ with _____ sacks cmt on top. CIBP #2: Depth _____ with _____ sacks cmt on top.
CIBP #3: Depth _____ with _____ sacks cmt on top. CIBP #4: Depth _____ with _____ sacks cmt on top.
CIBP #5: Depth _____ with _____ sacks cmt on top.

NOTE: Two(2) sacks cement required on all CIBPs.

Set _____ sks cmt from _____ ft. to _____ ft. Plug Type: _____ Plug Tagged: ☐
Set _____ sks cmt from _____ ft. to _____ ft. Plug Type: _____ Plug Tagged: ☐
Set _____ sks cmt from _____ ft. to _____ ft. Plug Type: _____ Plug Tagged: ☐
Set _____ sks cmt from _____ ft. to _____ ft. Plug Type: _____ Plug Tagged: ☐
Set _____ sks cmt from _____ ft. to _____ ft. Plug Type: _____ Plug Tagged: ☐

Perforate and squeeze at _____ ft. with _____ sacks. Leave at least 100 ft. in casing _____ CICR Depth

Perforate and squeeze at _____ ft. with _____ sacks. Leave at least 100 ft. in casing _____ CICR Depth

Perforate and squeeze at _____ ft. with _____ sacks. Leave at least 100 ft. in casing _____ CICR Depth

(Cast Iron Cement Retainer Depth)

Set 89 sacks half in. half out surface casing from 285 ft. to 0 ft. Plug Tagged: ☒

Set _____ sacks at surface

Cut four feet below ground level, weld on plate Above Ground Dry-Hole Marker: ☐ Yes ☐ No

Set _____ sacks in rat hole Set _____ sacks in mouse hole

Additional Plugging Information for Subsequent Report Only

Casing Recovered: _____ ft. of _____ inch casing

Surface Plug Setting Date: 06/08/2023 Cut and Cap Date: 06/20/2023 Number of Days from Setting Surface Plug to Capping or Sealing the Well: 12

*Wireline Contractor: _____

*Cementing Contractor: DUCO Inc. Cementing Services

Type of Cement and Additives Used: Class G 15.8 PPG Cement

Flowline/Pipeline has been abandoned per Rule 1105 ☐ Yes ☐ No

Technical Detail/Comments:

Eastman Kodak 1 (05-123-08111)/Re-Enter to Re-Plug Procedure

Original Abandon Date: 12/30/1974

Abandoned Formation: J Sand: 7572'-7600'

Upper Pierre Aquifer: Base: 1056'

Deepest Water Well: 300'

TD: 7710'

Surface Casing: 8 5/8" 24# @ 262' w/ 250 sxs cmt

Production Casing: 5 1/2" 15.5# @ 7685' w/ 270 sxs cmt (TOC @ 6750' - Calc)

Stage Tool @ 4200' w/ 335 sxs cmt (TOC @ 3010' - Calc)

Open Hole: 7 7/8" @ 3001'-262'

Existing Plugs: 7638'-7340' (40 sx cmt), 3200'-2890' (50 sx cmt), 430'-300' (50 sx cmt)

Procedure:

1. Dig out to find wellhead and check pressure.
2. Cut cap off, extend surface pipe to achieve ground level.
3. MIRU WO unit, ND wellhead, NU BOP, tally all pipe to be ran in well.
4. Wash run down to balance cement plug and tagged TOC at 285' (estimated to be ~300' according to the well history).
5. PU tubing to 285'. RU cementing company. Mix and pump 89 sxs 15.8#/gal CI G cement down tubing. Cement circulate to surface.
6. RDMO WO unit. Remove extension of surface pipe.
7. Weld on cap with ID plate, inscribed with well location, and identity. Backfill, clean location. Re-Entry complete.

I hereby certify all statements made in this form are, to the best of my knowledge, true, correct, and complete.

Signed: _____

Print Name: Valerie Danson

Based on the information provided herein, this Well Abandonment Report (Form 6) complies with COGCC Rules and applicable orders and is hereby approved.

COGCC Approved: Date:

CONDITIONS OF APPROVAL, IF ANY:

COA Type	Description
0 COA	

Attachment List

Att Doc Num	Name
403479240	CEMENT JOB SUMMARY
403479241	OTHER
403479242	OPERATIONS SUMMARY
403489920	WELLBORE DIAGRAM
403489922	OTHER

Total Attach: 5 Files

General Comments

User Group	Comment	Comment Date
		Stamp Upon Approval

Total: 0 comment(s)