

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, GRAND VALLEY-FEDERAL-67S96W/3NWSE

Location ID: 322529

Date: 8/7/2023



NW Corner of Location – Photo #05559



SW Corner of Location – Photo #05560

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, GRAND VALLEY-FEDERAL-67S96W/3NWSE

Location ID: 322529

Date: 8/7/2023



SE Corner of Location – Photo #05561



NE Corner of Location – Photo #05562



## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, GRAND VALLEY-FEDERAL-67S96W/3NWSE

Location ID: 322529

Date: 8/7/2023



Wellhead – Photo #05565



Separator – Photo #05567

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, GRAND VALLEY-FEDERAL-67S96W/3NWSE

Location ID: 322529

Date: 8/7/2023



Tank Battery – Photo #05568



Tank Label Missing Capacity – Photo #05569



## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, GRAND VALLEY-FEDERAL-67S96W/3NWSE

Location ID: 322529

Date: 8/7/2023



Aug 7, 2023 at 11:49:48  
Garden Gulch  
Parachute CO 81635  
United States



Aug 7, 2023 at 11:50:41  
Garden Gulch  
Parachute CO 81635  
United States

Location Lacks Stabilization – Photo #05566

Location Lacks Stabilization – Photo #05570



## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, GRAND VALLEY-FEDERAL-67S96W/3NWSE

Location ID: 322529

Date: 8/7/2023



**Insufficient Vehicle Tracking BMPs at Location Entrance/Exit  
– Photo #05571**



**Rill Erosion Cutting Through Lease Road – Photo #05610**



## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, GRAND VALLEY-FEDERAL-67S96W/3NWSE

Location ID: 322529

Date: 8/7/2023



Rill Erosion Cutting Through Lease Road – Photo #05613



Check Dam Needs Maintenance – Photo #05611