

**FORM
INSP**Rev
X/20

State of Colorado

Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

08/09/2023

Submitted Date:

08/09/2023

Document Number:

699107148

FIELD INSPECTION FORM

Loc ID 332047 Inspector Name: Burns, Adam On-Site Inspection ☐ 2A Doc Num: _____

Operator Information:

OGCC Operator Number: 65110

Name of Operator: O'BRIEN ENERGY RESOURCES CORP

Address: 18 CONGRESS ST STE 207

City: PORTSMOUTH State: NH Zip: 03801

Status Summary:☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

11 Number of Comments

3 Number of Corrective Actions

☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
Forma, Joseph	603-427-2099 x111	joeforma@obenergy.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
332047	LOCATION	AC			-	LOST CREEK-63N62W 21SWNW	SI

General Comment:

[This is an inspection on the tank battery](#)

LocationOverall Good: ☒

Signs/Marker:			
Type	TANK LABELS/PLACARDS		
Comment:	Pit needs placards. See attached photo.		
Corrective Action:	Install sign to comply with Rule 605.h.	Date:	09/22/2023
Type	BATTERY		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:	
Comment:	Adequate
Corrective Action:	
Date:	

Good Housekeeping:			
Type	WEEDS		
Comment:	Overgrown vegetation is starting to grown in the tank battery and needs to be removed for good housekeeping. See attached photo.		
Corrective Action:	Comply with Rule 606	Date:	09/22/2023
Type	TRASH		
Comment:	Unused Fence post needs to be removed for good housekeeping. See attached photo.		
Corrective Action:	Comply with Rule 606	Date:	09/22/2023

Overall Good: ☐

Spills:			
Type	Area	Volume	

In Containment: No

Comment: ☐ Multiple Spills and Releases?

Fencing/:			
Type	TANK BATTERY		
Comment:	Barbwire		
Corrective Action:		Date:	
Type	SEPARATOR		
Comment:	barbwire		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 1		
Comment:			

Corrective Action:		Date:	
--------------------	--	-------	--

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	1	300 BBLs	STEEL AST		40.213300,-104.335100

Comment:	
Corrective Action:	Date:

Paint

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate

Comment:	
Corrective Action:	Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	100 BBLs	CONCRETE SUMP/VAULT		,

Comment:	Missing placard
Corrective Action:	Date:

Paint

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance

Comment:	
Corrective Action:	Date:

Venting:

Yes/No	NO
Comment:	
Corrective Action:	Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected FacilitiesFacility ID: 332047 Type: LOCATION API Number: - Status: AC Insp. Status: SI**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned

Reminder: _____

Comment: si tank battery

Corrective Action: _____

Date: _____

COGCC Comments

Comment

User

Date

ECMC Inspection Report Summary

On Tuesday 8/8/23 at approximately 0957hrs I, Inspector Adam Burns, Conducted an on-site inspection at Lost Creek-63N62W 21SWNW of O'Brien Energy Resources Corp.

Location ID #332047 in Weld County, Colorado.

During this inspection the following possible compliance issues were observed:

Pit needs placard. Install sign to comply with Rule 605.h. With a Corrective Action date of 9/22/23

Overgrown vegetation is starting to grown in the tank battery and needs to be removed for good housekeeping. Comply with Rule 606. With a Corrective Action date of 9/22/23

Unused Fence post needs to be removed for good housekeeping. Comply with Rule 606.

With a Corrective Action date of 9/22/23

A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with ECMC rules.

This is a summary of the inspection report.

burnsa

08/09/2023

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699107149	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6213439