

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

08/09/2023

Submitted Date:

08/09/2023

Document Number:

699107162**FIELD INSPECTION FORM**Loc ID 331757 Inspector Name: Burns, Adam On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 65110Name of Operator: O'BRIEN ENERGY RESOURCES CORPAddress: 18 CONGRESS ST STE 207City: PORTSMOUTH State: NH Zip: 03801**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:10 Number of Comments5 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Forma, Joseph	603-427-2099 x111	joeforma@obenergy.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
331757	LOCATION	AC			-	NORTH LOST CREEK- 63N62W 20SWNE	SI

General Comment:[This is an inspection on the Tank Battery](#)

LocationOverall Good: ☒

Signs/Marker:			
Type	TANK LABELS/PLACARDS		
Comment:	Missing capacity Label for the pit. See attached photo.		
Corrective Action:	Install sign to comply with Rule 605.h.		Date: 09/22/2023
Type	TANK LABELS/PLACARDS		
Comment:	Missing NFPA placard for the pit. See attached photo.		
Corrective Action:	Install sign to comply with Rule 605.h.		Date: 09/22/2023
Type	BATTERY		
Comment:	Missing Battery sign		
Corrective Action:	Install sign to comply with Rule 605.a.		Date: 09/22/2023

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type	WEEDS		
Comment:	Overgrown vegetation around the tank battery needs to be removed for good housekeeping. See attached photos.		
Corrective Action:	Comply with Rule 606.		Date: 09/22/2023

Overall Good: ☐

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

☐ Multiple Spills and Releases?

Fencing/:			
Type	TANK BATTERY		
Comment:	Barbwire		
Corrective Action:			Date:

Equipment:			corrective date
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:			Date:
Type: Other	#		
Comment:	Unmarked risers need marked. See attached photos		
Corrective Action:	Upon removing a flowline or crude oil transfer line from use with the intent to abandon, an operator must immediately apply OOSLAT to the risers. OOSLAT must stay in place at all times during the process of abandoning the flowline or crude oil transfer line until the operator removes the riser. Comply with Rule 1105.b.		Date: 09/22/2023
Type: Pig Station	# 1		

Comment:			
Corrective Action:		Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected FacilitiesFacility ID: 331757 Type: LOCATION API Number: - Status: AC Insp. Status: SI**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned Reminder: _____Comment: si tank battery

Corrective Action: _____ Date: _____

COGCC Comments

Comment	User	Date
<p>ECMC Inspection Report Summary</p> <p>On Tuesday 8/8/23 at approximately 1040hrs I, Inspector Adam Burns, Conducted an on-site inspection at North Lost Creek-63N62W 20SWNE Tank Battery of O'Brien Energy Resources Corp.</p> <p>Location ID #331757 in Weld County, Colorado.</p> <p>During this inspection the following possible compliance issues were observed:</p> <p>Missing pit capacity label. Install sign to comply with Rule 605.h. With a Corrective Action date of 9/22/23</p> <p>Missing NFPA placard for the pit. Install sign to comply with Rule 605.h. With a Corrective Action date of 9/22/23</p> <p>Missing Battery sign. Install sign to comply with Rule 605.a. With a Corrective Action date of 9/22/23</p> <p>Overgrown vegetation around the tank battery needs to be removed for good housekeeping. Comply with Rule 606. With a Corrective Action date of 9/22/23</p> <p>Unmarked risers need marked. Upon removing a flowline or crude oil transfer line from use with the intent to abandon, an operator must immediately apply OOSLAT to the risers. OOSLAT must stay in place at all times during the process of abandoning the flowline or crude oil transfer line until the operator removes the riser. Comply with Rule 1105.b. With a Corrective Action date of 9/22/23</p> <p>A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with ECMC rules.</p> <p>This is a summary of the inspection report.</p>	burnsa	08/09/2023

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699107163	Inspection photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6213446