

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

08/08/2023

Submitted Date:

08/10/2023

Document Number:

713600069

**FIELD INSPECTION FORM**Loc ID 308323 Inspector Name: COSTA, RYAN On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

OGCC Operator Number: 10705

Name of Operator: EVERGREEN NATURAL RESOURCES LLC

Address: 1875 LAWRENCE ST STE 1150

City: DENVER State: CO Zip: 80202

**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

4 Number of Comments

2 Number of Corrective Actions

- ☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Inspections, Evergreen		cogcc.evergreen@enrllc.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
266620	WELL	PR	04/09/2004	GW	071-07829	COW CAMP 41-5	RI
270493	PIT	AC	12/17/2003		-	COW CAMP 41-5 ONSITE	AC

**General Comment:**

On 8/8/2023, Ryan Costa conducted a follow up stormwater management and pit inspection.  
See attached photos and additional details within this report.

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: No stormwater issues were observed at the location during inspection.

Corrective Action:

Date: \_\_\_\_\_

**Pits:** ☐ NO SURFACE INDICATION OF PITType: Produced Water Lined: \_\_\_\_\_ Pit ID: 270493 Lat: 37.033575 Long: -104.686353

Reference Point: \_\_\_\_\_ Other: \_\_\_\_\_ Length: \_\_\_\_\_ Width: \_\_\_\_\_

**Lining:**

Liner Type:

Liner Condition:

Comment:

The pit is not constructed to allow 2 ft. freeboard. The freeboard marker is laying flat on the ground. There are signs of whitened soils from possible water from the pit overflowing across the location. Pit needs to be constructed to maintain freeboard. Corrective action will remain out of compliance until completed.

Corrective Action

Comply with Rule 909.c

Date: 08/08/2023**Fencing:**

Fencing Type:

Fencing Condition:

Comment:

Corrective Action

Date:

**Netting:**

Netting Type:

Netting Condition:

Comment:

Corrective Action

Date:

Anchor Trench Present:

Oil Accumulation: NO2+ feet Freeboard: NOComment: Water level was above 2 ft. freeboard.

Corrective Action

Lower fluid level so at least two feet of freeboard exists per Rule 909.c

Date: 08/08/2023

Permit:	Facility ID	Permit Num	Expiration Date
	270493	1126104	
	270493	1126104	

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
713600070	Inspection Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6214365">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6214365</a>