

FORM  
INSPRev  
X/20State of Colorado  
Oil and Gas Conservation Commission1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

08/10/2023

Submitted Date:

08/10/2023

Document Number:

699107168

## FIELD INSPECTION FORM

Loc ID \_\_\_\_\_ Inspector Name: \_\_\_\_\_ On-Site Inspection   
 317489 Burns, Adam 2A Doc Num: \_\_\_\_\_

**Operator Information:**

OGCC Operator Number: 46290  
 Name of Operator: KP KAUFFMAN COMPANY INC  
 Address: 1700 LINCOLN ST STE 4550  
 City: DENVER State: CO Zip: 80203

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION  
 FOLLOW UP INSPECTION REQUIRED  
 NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

- 8 Number of Comments  
 3 Number of Corrective Actions  
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM  
 PREVIOUS INSPECTIONS THAT HAVE NOT  
 BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
,		cogcc@kpk.com	All Inspections

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
238228	WELL	PR	01/01/2023	GW	123-05061	SHOE 1	SI

**General Comment:**

this is an inspection on the well

Location			
<b>Lease Road:</b>			
Type	Access		
comment:	Access road is overgrown with vegetation and needs to be removed for good housekeeping. See attached photo.		
Corrective Action:	Comply with Rule 606		Date: 09/22/2023
Overall Good: <input type="checkbox"/>			
<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:	Well sign does not reflect current operator. See attached photo.		
Corrective Action:	Install sign to comply with Rule 605.d.		Date: 09/22/2023
<b>Emergency Contact Number:</b>			
Comment:	<input style="width: 100%;" type="text"/>		
Corrective Action:	<input style="width: 100%;" type="text"/>		Date: _____
<b>Good Housekeeping:</b>			
Type	WEEDS		
Comment:	Overgrown vegetation in and around the well location, needs to be removed for good housekeeping. See attached photo.		
Corrective Action:	Comply with Rule 606.		Date: 09/22/2023
Overall Good: <input type="checkbox"/>			
<b>Spills:</b>			
Type	Area	Volume	
In Containment: No			
Comment:	<input style="width: 100%;" type="text"/>		
<input type="checkbox"/> Multiple Spills and Releases?			
<b>Fencing/:</b>			
Type	WELLHEAD		
Comment:	Panel		
Corrective Action:			Date:
<b>Equipment:</b>			
Type: Bradenhead	# 1		corrective date
Comment:			
Corrective Action:			Date:
Type: Plunger Lift	# 1		
Comment:			
Corrective Action:			Date:
<b>Venting:</b>			
Yes/No	NO		
Comment:			
Corrective Action:			Date:
<b>Flaring:</b>			

Type		
Comment:		
Corrective Action:		Date:

**Inspected Facilities**

Facility ID: 238228 Type: WELL API Number: 123-05061 Status: PR Insp. Status: SI

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: \_\_\_\_\_

Comment: SI at the seperator

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**BradenHead**

Date of Last Brhd Test: 04/26/2023 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: \_\_\_\_\_

End Surf Csg Pressure: 0

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**COGCC Comments**

Comment	User	Date
<p><a href="#">ECMC Inspection Report Summary</a>                      On Thursday 8/10/23 at approximately 0928hrs I, Inspector Adam Burns, Conducted an on-site inspection at Shoe 1 of KP Kauffman Company Inc. API #05-123-05061 in Weld County, Colorado.                      During this inspection the following possible compliance issues were observed:                      Well sign does not reflect current operator. Install sign to comply with Rule 605.d. With a Corrective Action date of 9/22/23                      Access road is overgrown with vegetation and needs to be removed for good housekeeping. Comply with Rule 606. With a Corrective Action date of 9/22/23                      Overgrown vegetation in and around the well location, needs to be removed for good housekeeping. Comply with Rule 606. With a Corrective Action date of 9/22/23                      A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with ECMC rules.                      This is a summary of the inspection report.</p>	burnsa	08/10/2023

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699107169	Inspection Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6215227">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6215227</a>