



OIL AND GAS CONSERVATION COMMISSION OF THE STATE OF COLORADO



PLUGGING RECORD

INSTRUCTIONS

Within thirty (30) days after the plugging of any well, the owner or operator thereof shall file this form in duplicate for wells on Patented or Federal lands, and in triplicate for wells on State lands, give a detailed account of the manner in which the abandonment or plugging work was carried out, including the nature and quantities of materials used in plugging and the location and extent (by depths) of the plugs of different materials; records of the amount, size and location (by depths) of casings and junk left in the well; and a detailed statement of the volume and weight of mud fluid used.

Operator J. M. Huber Corporation Field Brandon Wildeat No.
Lease Name Harrison State Well No. 1 County Kiowa
Location C NE/4 NE/4 Section 16 Township 19S Range 45W Meridian
660 feet from N Section line and 660 feet from E Section Line
N or S E or W

TOTAL DEPTH 4160' DATE OF PLUGGING 5-20-61

DETAILS OF WORK

Filled hole with drilling mud from total depth back to surface. Spotted 25 sacks cement from 3982' - 4007'. Spotted 25 sacks from 3762' - 3780'. Spotted 10 sacks in bottom of 13-3/8" surface casing. Plugged top of hole with 5 sacks.

Left 155' 13-3/8" surface casing in hole.

4/23/61 Cem. in csg. Pits still full not leveled. JB

plugging out in by Jervis May 23/61

BEST IMAGE AVAILABLE

Table with 2 columns and 7 rows: AJJ, DVR, WRS, HHM, JAM, FJP, JJD, FILE

I/we hereby swear (or affirm) that the statements herein made are a full and correct report:

Approved: Date MAY 24 1961 Company J. M. Huber Corp. Date 5-23-61
Address Denver 6, Colorado Phone No. DU 8-5781
Director A. J. Jervis By [Signature] Title Petr. Engr.

Hack wants Present Status

4-24-78

P.S.

*[Handwritten signature]*

5/16/78 - Inopco called.  
They will send in fm 4 -  
weel still s.I.

AM

BEST IMAGE  
AVAILABLE

9/21/72

Called for status of 1-16  
state. It was supposed  
to be abandoned per  
Order No. 188-11 (findings)  
They will send in fm. 4  
stating that it was  
Temp. Abd. because the  
1-16X was such a  
poor well.

Hack

ALL
DVE
WSS
HHH
JAM
...
...
...
...
...