

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

08/09/2023

Submitted Date:

08/09/2023

Document Number:

699107142

**FIELD INSPECTION FORM**

Loc ID 310583 Inspector Name: Burns, Adam On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 65110  
Name of Operator: O'BRIEN ENERGY RESOURCES CORP  
Address: 18 CONGRESS ST STE 207  
City: PORTSMOUTH State: NH Zip: 03801

**Findings:**

- 8 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
		dnr_cogccengineering@state.co.us	
Forma, Joseph		joeforma@obenergy.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
293807	WELL	PR	09/01/2021	GW	123-26623	LOST CREEK 42	PR

**General Comment:**

[Inspection on the well](#)

**Location**

Overall Good:

**Signs/Marker:**

Type	OTHER		
Comment:	Sign on gate into location		
Corrective Action:		Date:	

**Emergency Contact Number:**

Comment:	Adequate	Date:	
Corrective Action:			

Overall Good:

**Spills:**

Type	Area	Volume			

In Containment: No

Comment:

Multiple Spills and Releases?

**Fencing/:**

Type	LOCATION		
Comment:	Barbwire		
Corrective Action:		Date:	

**Equipment:**

					corrective date
Type: Bradenhead	# 1				
Comment:					
Corrective Action:		Date:			
Type: Plunger Lift	# 1				
Comment:					
Corrective Action:		Date:			

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type			
Comment:			
Corrective Action:		Date:	

**Inspected Facilities**

Facility ID: 293807 Type: WELL API Number: 123-26623 Status: PR Insp. Status: PR

**Producing Well**

Comment: PR

Corrective Action:

Date:

**BradenHead**

Date of Last Brhd Test: 12/01/2021 Annual Brhd Completed? No

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: NONE

End Surf Csg Pressure: 0

Comment: No updated annual BH test on file. Submit reports. Form 17 #403256953 indicates it was last tested on 12/1/20

09/22/2023

Corrective Action: Submit reports as per Rule 207.

Date:

**COGCC Comments**

Comment	User	Date
<p><b>ECMC Inspection Report Summary</b>                      On Tuesday 8/8/23 at approximately 0944hrs I, Inspector Adam Burns, Conducted an on-site inspection at South Lost Creek 42 of O'Brien Energy Resources Corp.                      API #05-123-26623 in Weld County, Colorado.                      During this inspection the following possible compliance issues were observed:                      No updated annual BH test on file. Submit reports. Form 17 #403256953 indicates it was last tested on 12/1/20. Submit reports as per Rule 207. With a Corrective Action date of 9/22/23                      A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with ECMC rules.                      This is a summary of the inspection report.</p>	burnsa	08/09/2023

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403492003	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6213450">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6213450</a>
699107143	Inspection Photo	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6213436">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6213436</a>