

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

08/09/2023

Submitted Date:

08/09/2023

Document Number:

699107146

FIELD INSPECTION FORM

Loc ID 332047 Inspector Name: Burns, Adam On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 65110
Name of Operator: O'BRIEN ENERGY RESOURCES CORP
Address: 18 CONGRESS ST STE 207
City: PORTSMOUTH State: NH Zip: 03801

Findings:

- 8 Number of Comments
- 2 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
		dnr_cogccengineering@state.co.us	
Forma, Joseph	603-427-2099 x111	joeforma@obenergy.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
269876	WELL	SI	12/01/2019	GW	123-21760	LOST CREEK 14	TA

General Comment:

[Form 06A on file. MIT was done on 5/24/22](#)

Location

Overall Good:

Signs/Marker:

Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:	Adequate		
Corrective Action:		Date:	

Good Housekeeping:

Type	OTHER		
Comment:	Stained soil around the well needs to be removed for good housekeeping. See attached photo.		
Corrective Action:	"Properly dispose of oily waste in accordance with 905.e."		Date: 09/22/2023

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

Type	WELLHEAD		
Comment:	Panel		
Corrective Action:		Date:	

Equipment:

Equipment	#	Corrective Action	Date
Type: Plunger Lift	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:			
Corrective Action:		Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 269876 Type: WELL API Number: 123-21760 Status: SI Insp. Status: TA

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment: T/A

Corrective Action: _____ Date: _____

BradenHead

Date of Last Brhd Test: 11/27/2021 Annual Brhd Completed? No

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: NONE

End Surf Csg Pressure: 0

Comment: No updated annual BH test on file. Submit reports. Form 17 #403256966 indicates it was last tested on 12/8/20. 09/22/2023

Corrective Action: Submit reports as per Rule 207. Date: _____

COGCC Comments

Comment	User	Date
<p>ECMC Inspection Report Summary On Tuesday 8/8/23 at approximately 0957hrs I, Inspector Adam Burns, Conducted an on-site inspection at South Lost Creek 14 of O'Brien Energy Resources Corp. API #05-123-21760 in Weld County, Colorado. During this inspection the following possible compliance issues were observed: Stained soil around the well needs to be removed for good housekeeping. "Properly dispose of oily waste in accordance with 905.e." With a Corrective Action date of 9/22/23 No updated annual BH test on file. Submit reports. Form 17 #403256966 indicates it was last tested on 12/8/20. Submit reports as per Rule 207. With a Corrective Action date of 9/22/23 A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with ECMC rules. This is a summary of the inspection report.</p>	burnsa	08/09/2023

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403492013	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6213456
699107147	Inspection photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6213438