

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

08/09/2023

Submitted Date:

08/09/2023

Document Number:

699107148

FIELD INSPECTION FORMLoc ID 332047 Inspector Name: Burns, Adam On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 65110

Name of Operator: O'BRIEN ENERGY RESOURCES CORP

Address: 18 CONGRESS ST STE 207

City: PORTSMOUTH State: NH Zip: 03801

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

11 Number of Comments

3 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Forma, Joseph	603-427-2099 x111	joeforma@obenergy.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
332047	LOCATION	AC			-	LOST CREEK-63N62W 21SWNW	SI

General Comment:[This is an inspection on the tank battery](#)

LocationOverall Good: ☒

Signs/Marker:			
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	Pit needs placards. See attached photo.		
Corrective Action:	Install sign to comply with Rule 605.h.	Date:	09/22/2023

Emergency Contact Number:

Comment: Adequate

Corrective Action: _____ Date: _____

Good Housekeeping:

Type	WEEDS		
Comment:	Overgrown vegetation is starting to grown in the tank battery and needs to be removed for good housekeeping. See attached photo.		
Corrective Action:	Comply with Rule 606	Date:	09/22/2023
Type	TRASH		
Comment:	Unused Fence post needs to be removed for good housekeeping. See attached photo.		
Corrective Action:	Comply with Rule 606	Date:	09/22/2023

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: _____

☐ Multiple Spills and Releases?**Fencing/:**

Type	SEPARATOR		
Comment:	barbwire		
Corrective Action:		Date:	
Type	TANK BATTERY		
Comment:	Barbwire		
Corrective Action:		Date:	

Equipment:

Type: Bird Protectors	# 1		corrective date
Comment:			
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 1		
Comment:			

Corrective Action:		Date:	
--------------------	--	-------	--

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	1	300 BBLs	STEEL AST		40.213300,-104.335100

Comment:	
Corrective Action:	Date:

Paint

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate

Comment:	
Corrective Action:	Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	100 BBLs	CONCRETE SUMP/VAULT		,

Comment:	Missing placard
Corrective Action:	Date:

Paint

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance

Comment:	
Corrective Action:	Date:

Venting:

Yes/No	NO
Comment:	
Corrective Action:	Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected FacilitiesFacility ID: 332047 Type: LOCATION API Number: - Status: AC Insp. Status: SI**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned

Reminder: _____

Comment: si tank battery

Corrective Action: _____

Date: _____

COGCC Comments

Comment	User	Date
<p>ECMC Inspection Report Summary</p> <p>On Tuesday 8/8/23 at approximately 0957hrs I, Inspector Adam Burns, Conducted an on-site inspection at Lost Creek-63N62W 21SWNW of O'Brien Energy Resources Corp.</p> <p>Location ID #332047 in Weld County, Colorado.</p> <p>During this inspection the following possible compliance issues were observed:</p> <p>Pit needs placard. Install sign to comply with Rule 605.h. With a Corrective Action date of 9/22/23</p> <p>Overgrown vegetation is starting to grown in the tank battery and needs to be removed for good housekeeping. Comply with Rule 606. With a Corrective Action date of 9/22/23</p> <p>Unused Fence post needs to be removed for good housekeeping. Comply with Rule 606. With a Corrective Action date of 9/22/23</p> <p>A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with ECMC rules.</p> <p>This is a summary of the inspection report.</p>	burnsa	08/09/2023

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403492014	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6213457
699107149	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6213439