

State of Colorado  
Energy & Carbon Management Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

403400137

Date Received:

05/11/2023

## FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

1 of 2 CAs from the FIR responded to on this Form

1 CA Completed  
0 Factual Review Request

### OPERATOR INFORMATION

OGCC Operator Number: 10779

Name of Operator: SCOUT ENERGY MANAGEMENT LLC

Address: 13800 MONTFORT DRIVE SUITE 100

City: DALLAS State: TX Zip: 75240

Contact Name and Telephone:

Name: \_\_\_\_\_

Phone: ( ) \_\_\_\_\_ Fax: ( ) \_\_\_\_\_

Email: \_\_\_\_\_

Additional Operator Contact:

Contact Name	Phone	Email
<u>Patterson, Chris</u>		<u>Chris.Patterson@scoutep.com</u>
<u>Fischer, Alex</u>		<u>alex.fischer@state.co.us</u>
<u>*</u>		<u>RangelyRegulatory@scoutep.com</u>
<u>Sanford, Anita</u>		<u>Anita.Sanford@scoutep.com</u>
<u>Johnson, Mike</u>		<u>Mike.Johnson@scoutep.com</u>
<u>Heil, John</u>		<u>john.heil@state.co.us</u>

### COGCC INSPECTION SUMMARY:

FIR Document Number: 696204864

Inspection Date: 04/24/2023

FIR Submit Date: 04/25/2023

FIR Status: \_\_\_\_\_

#### Inspected Operator Information:

Company Name: OLD OPERATORS - STATUS UNKNOWN

Company Number: 99999

Address: SEE COMMENT LINE IN WELL

City: XXXXXXX State: XX Zip: \_\_\_\_\_

#### LOCATION - Location ID: 479691

Location Name: RUNKNOWN Number: 33-18 County: \_\_\_\_\_

Qtrqtr: NWS Sec: 33 Twp: 2N Range: 102W Meridian: 6  
W

Latitude: 40.099010 Longitude: -108.857060

#### FACILITY - API Number: 05-103- -00 Facility ID: 479691

Facility Name: RUNKNOWN Number: 33-18

Qtrqtr: NWS Sec: 33 Twp: 2N Range: 102W Meridian: 6  
W

Latitude: 40.099010 Longitude: -108.857060

### CORRECTIVE ACTIONS:

2 ☒ CA# 170066

Corrective Action: Within 48 hours, Operator shall:

Date: 04/27/2023

- 1) Contact NW EPS John Heil (John.heil@state.co.us)
- 2) Comply with Rule 913.g and send a Form 27 for change of Operator.
- 3) Comply with 913.b.(5)B.i and install fencing or cover at the excavation.
- 4) Comply with Rules 913.b.(5)B.ii and 1002.c, and install BMPs to protect the stockpile, as well as to minimize erosion, degradation and sediment transport.

Upon closure of the Facility, Operator is required to conduct final reclamation pursuant to Rules 913.b.(6) and 1004.a.

Response: CA COMPLETED

Date of Completion: 05/09/2023

Operator Comment: Talked with John Heil with the COGCC via phone call, on April 25th at 1:06 PM  
Summited F27 for change of operator DOC# 403383712.  
Installed fencing at excavation.  
Installed BMPs to protect the stockpile  
Re-situated the Waddles around the stock piles so there are no gaps.

COGCC Decision: Approved pending re-inspection

COGCC Representative: Approved pending re-inspection of this FIR resolution acknowledges the document was received. It is not an acknowledgement that the corrective action has been passed. A field inspection will be conducted at a future date to evaluate compliance with ECMC rules.

#### OPERATOR COMMENT AND SUBMITTAL

Comment: Please see Attachment

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Chris Patterson

Signed: \_\_\_\_\_

Title: Sr. HSE Coordinator

Date: 5/11/2023 7:04:30 AM

### **ATTACHMENT LIST**

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
403400137	FIR RESOLUTION SUBMITTED
403400142	PIC

Total Attach: 2 Files