



COLORADO OIL & GAS CONSERVATION COMMISSION

FIELD INSPECTION REPORT

MAY 13 1996



<input checked="" type="checkbox"/> NOTICE OF UNSATISFACTORY INSPECTION		1120 Lincoln Street, Suite 801 Denver, CO 80203 (303)894-2100	
<input type="checkbox"/> NOTICE OF SATISFACTORY INSPECTION			
API No. 05- 009 - 6079		LEASE NAME: L. HAMILTON #1	
LOCATION: NESW34-345-41W		OPERATOR: DONALD JACKSON	
DATE: 4-8-96.		INSPECTOR: R. Vansickle	
Insp. Type: PR	Insp. Status: PR	PA: Y N	Pass/Fail: <input checked="" type="radio"/> P <input type="radio"/> F Viol.: <input checked="" type="radio"/> Y <input type="radio"/> N NOV: Y N

INSPECTION ITEM	COMMENTS	INPUT
Well ID Signs (Rule 210)	No emergency phone numbers.	✓
Pits (Reserve/Production) (Rule 902, 903, 904)	None.	
Fences (Rule 604.C.(3), 1003.A)	Around site.	
Tank Battery Equipment (Rule 604)	sep, GMR, pump unit, 100 BBL wtr tank.	✓
Fire Walls/Berms/Dikes (Rule 604)	None.	✓
General Housekeeping (Rule 603.G)	OK.	
Spills (Oil/Water) (Rule 908)	None.	
Bradenhead (Rule 207)	—	
Drilling Well/Workover (Rule 315)	—	
Surface Rehabilitation (Rule 317)	—	
Miscellaneous	—	

CORRECTIVE ACTION REQUIRED: Install berms, update sign -
7-15-96

Date Corrective Action Required By: 6-8-96 Date Remedied:

This report is a Notice of Inspection. The Commission requires that you correct any deficiencies shown on this report in a timely manner. Failure to comply may result in enforcement action by the Commission.

White - File Green - Operator Canary - Well Site

BOB VANSICKLE 719/336-2843