

State of Colorado  
Energy & Carbon Management Commission



1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Document Number:  
403301294

Date Received:  
01/25/2023

**FIR RESOLUTION FORM**

Overall Status: CAC

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed  
0 Factual Review Request

**OPERATOR INFORMATION**

OGCC Operator Number: 10749

Name of Operator: SIMCOE LLC

Address: 1199 MAIN AVE SUITE 101

City: DURANGO State: CO Zip: 81301

Contact Name and Telephone:

Name: \_\_\_\_\_

Phone: ( ) \_\_\_\_\_ Fax: ( ) \_\_\_\_\_

Email: \_\_\_\_\_

Additional Operator Contact:

Contact Name	Phone	Email
<u>General</u>		<u>sjninspections@ikavenergy.com</u>

**COGCC INSPECTION SUMMARY:**

FIR Document Number: 693904113

Inspection Date: 01/19/2022 FIR Submit Date: 01/21/2022 FIR Status: \_\_\_\_\_

Inspected Operator Information:

Company Name: SIMCOE LLC Company Number: 10749

Address: 1199 MAIN AVE SUITE 101

City: DURANGO State: CO Zip: 81301

LOCATION - Location ID: 312063

Location Name: BONDAD 33-9-N33N9W Number: 6SENE County: LA PLATA

Qtrqtr: SENE Sec: 6 Twp: 33N Range: 9W Meridian: N

Latitude: 37.135877 Longitude: -107.861612

FACILITY - API Number: 05-067-00 Facility ID: 259759

Facility Name: HUNGERFORD A Number: 2

Qtrqtr: SENE Sec: 6 Twp: 33N Range: 9W Meridian: N

Latitude: 37.135877 Longitude: -107.861612

**CORRECTIVE ACTIONS:**

1  CA# 159302

Corrective Action: -Control weeds by 6/1/2022.  
-Revegetation needs to be installed within the southern project area by 5/1/2022. Date: 05/01/2022

Response: CA COMPLETED Date of Completion: 01/25/2023

Operator Comment: Treated noxious weeds with chemical treatment as documented in FIRR #693904113 and #403121809. The area designated for reseeding is outside the area of wellsite and is under the landowner's control. See the attached aerial with the pad dimensions overlaid. Using the tree as a reference point, the southern area called out for correction is not part of the operator's built pad (flat or slopes). Referencing LOGOS's response FIRR #403024660 and its photos LOGOS appears to have addressed this inspection item.

COGCC Decision: Approved pending re-inspection

COGCC Representative:

[Empty box for COGCC Representative signature]

**2**  CA# 159303

Corrective Action: Stormwater (BMPs) and erosion controls (ie: mulch) need to be installed in the southern project area by 5/1/2022. Stormwater and erosion controls need to be installed and maintained until area is stabilized with desirable perennial vegetation.

Date: 05/01/2022

Response: CA COMPLETED

Date of Completion: 01/25/2023

Operator Comment: The area designated for stormwater controls is outside the area of wellsite and is under the landowner's control. See the attached aerial with the pad dimensions overlayed. Using the tree as a reference point, the southern area called out for correction is not part of the operator's built pad (flat or slopes). Referencing LOGOS's response FIR #403024660 and its photos LOGOS appears to have addressed this inspection item.

COGCC Decision: **Not Approved**

COGCC Representative: Operator response does not demonstrate that corrective action is completed. Disagreement with inspection findings under certain circumstances can be submitted as a factual review request within 10 days of receiving inspection (see website for guidance). Additionally, it is the responsibility of both operators on a shared well pad to maintain compliance with surface regulations. The attached overlayed plat does not demonstrate the extent of Simcoe's responsibility for surface management.

OPERATOR COMMENT AND SUBMITTAL

Comment: The area designated for operator response is outside the operator's built pad (including slopes).

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Katherine Feir

Signed: \_\_\_\_\_

Title: Compliance Coordinator

Date: 1/25/2023 11:07:12 AM

**ATTACHMENT LIST**

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
403301294	FIR RESOLUTION SUBMITTED
403301317	map and aerial showing extent of pad

Total Attach: 2 Files