

Weld OEM Spill Report Form

Submitted on	30 August 2023, 8:33AM
Receipt number	1312
Related form version	17

Company

Company name	Civitas Resources
Address	650 Southgate Drive
City	Windsor
State	Colorado
Zip code	80550

Contact Information

Contact person	Costin McQueen
Contact phone	720-384-6452
Contact email	cmcqueen@civiresources.com

About the Spill

Date incident occurred	08/29/2023
Was 9-1-1 called for this incident	No
Longitude	-104.722836
Latitude	40.438853
Fire depatment/district	Western Hills Fire
Where did the incident occur?	Oil and gas facility/pipeline

Oil and Gas Incident

Well site name	C Street Directional
----------------	----------------------

Section	36
Township	6N
Range	66W
Where did the spill occur	Dump line
Have you submitted a form 19	Yes
Form 19 report number	403515090

Product Spilled

Product spilled	produced water
Number of barrels spilled	2
Emergency precautions taken	N/A
Extremely hazardous substance	No
Acute or chronic health risks	No
Did the spill affect or end near a waterway, irrigation ditch, or a retention pond?	No
What caused the spill/release?	Weld or joint failure

Narrative

Include specific incident information and mitigation actions taken to stop and clean-up the spill/release

A pinhole in the CS Bittersweet 03-01-13 separator above ground water dump line resulted in approximately 2.65 bbls of produced water to be spilled to the ground surface. The spill was contained entirely on pad and a vac truck was dispatched to clean up surficial fluid. The impacted soil will be removed and hauled for disposal. Confirmation soil samples will be collected in compliance with ECMC Table 915-1. Additionally, a waste characterization sample will be collected and submitted for analysis of Table 915 constituents. Analytical results will be provided on a supplemental Form 19. The location is within the Bald Eagle Roost Site HPH buffer zone.

Acknowledgement

I acknowledge that a written follow-up notice must be submitted to Weld County OEM/LEPC as soon as practicable after the release. The follow-up notice must update information included in the initial notice and provide information on actual response actions taken and advice regarding medical attention necessary for citizens exposed.