

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

08/29/2023

Submitted Date:

08/30/2023

Document Number:

702501781

**FIELD INSPECTION FORM**Loc ID 316241 Inspector Name: Burchett, Kirby On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

OGCC Operator Number: 10775

Name of Operator: KT RESOURCES LLC

Address: 3381 WESTBROOK LANE

City: HIGHLANDS State: CO Zip: 80129

**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

13 Number of Comments

4 Number of Corrective Actions

- ☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Gale, Tony	(303) 886-8733	tony@kt-res.com	
Adams, Karen	(303) 886-8733	adams@kt-res.com	
Baumgras, Dan	(307) 321-3299	Dan@KT-Res.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
259422	WELL	SI	04/01/2023	GW	103-10092	WRD WYATT 36-14	SI

**General Comment:****ECMC Inspection Report Summary**

On Tuesday, 8/29/2023, Inspector Kirby Burchett, conducted a follow up field inspection at KT Resources LLC on the WRD Wyatt 36-14 well, Location #316241, in Rio Blanco County, Colorado.

This location is within or in close proximity to a Parks and Wildlife (CPW) District with High Priority, NSO, Density, and Other Consultation Habitat regulations.

Any Corrective Actions from previous Inspections are still applicable.

Follow up inspection to verify compliance issues observed during Inspections #702501018 on 3/21/23 and #702501279 on 5/9/23 have been resolved. No action has been taken to resolve Stormwater BMP issues. Due date will remain 6/7/23.

While there during normal production operations the following compliance issues were observed:

1. Weeds.
  2. Stained soil at tank battery.
  3. Ground stains below tank burner.
  4. Gas meter calibration card not in compliance.
  5. Stormwater BMPs have not been implemented or maintained.
- Refer to Inspection Photos for observed compliance issues.

A follow up on this site inspection will be conducted to ensure all compliance issues have been corrected to comply with ECMC rules.

**Location**Overall Good: ☐**Signs/Marker:**

Type	OTHER		
Comment:	As Location Entrance signs are replaced: The Well name; The Commission's Location identification number (ID #); The Operator's telephone number where it may be reached at all times; and the Telephone number(s) for local emergency services (911 where available) will be required.		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	CONTAINERS		
Comment:	Chemical tank on containment		
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	As Wellhead signs are replaced: The Well name; The API Number; and Its legal location, including the quarter/quarter section will be required.		
Corrective Action:		Date:	

**Emergency Contact Number:**

Comment: (800) 288-0560 or 911

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

Type	WEEDS		
Comment:	Oil and Gas Locations will be kept free of all Undesirable Plant Species.		
Corrective Action:	Maintain noxious weed control on all disturbed and reclaimed areas as a result of Oil & Gas activities including access roads.	Date:	09/06/2023

Overall Good: ☐**Spills:**

Type	Area	Volume		
PW/CO	Tank	<= 1 bbl		
Comment:	Soil staining at loadout valve and tank burner			
Corrective Action:	Remove and properly dispose of oily waste and impacted soil.			Date: 09/14/2023

In Containment: Yes

Comment:

☐ Multiple Spills and Releases?**Equipment:**

Type: Gas Meter Run	# 1		corrective date
---------------------	-----	--	-----------------

Comment:	Gas meter calibration displayed but out of compliance.			
Corrective Action:	Meters will be calibrated annually unless more frequent calibration is required by contractual obligations.		Date:	09/09/2023
Type: Deadman # & Marked	# 4			
Comment:				
Corrective Action:			Date:	
Type: Ancillary equipment	# 1			
Comment:	Chemical tank on containment			
Corrective Action:			Date:	
Type: Plunger Lift	# 1			
Comment:				
Corrective Action:			Date:	
Type: Bird Protectors	# 2			
Comment:				
Corrective Action:			Date:	
Type: Horizontal Heater Treater	# 1			
Comment:				
Corrective Action:			Date:	
Type: Bradenhead	# 1			
Comment:				
Corrective Action:			Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	1	300 BBLS	HEATED STEEL AST		,
Comment:					
Corrective Action:					Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Other	Adequate				
Comment:	Unlined metal and earth.				
Corrective Action:				Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	300 BBLS	STEEL AST		,
Comment:					

Corrective Action:		Date:	
<b>Paint</b>			
Condition	Adequate		
Other (Content)			
Other (Capacity)			
Other (Type)			
<b>Berms</b>			
Type	Capacity	Permeability (Wall)	Maintenance
Other	Adequate		
Comment: <a href="#">Unlined metal and earth.</a>			
Corrective Action:		Date:	
<b>Venting:</b>			
Yes/No	NO		
Comment:			
Corrective Action:			Date:
<b>Flaring:</b>			
Type			
Comment:			
Corrective Action:			Date:

Inspected Facilities									
Facility ID:	259422	Type:	WELL	API Number:	103-10092	Status:	SI	Insp. Status:	SI
Idle Well									
Purpose: <input checked="" type="checkbox"/> Shut In <input type="checkbox"/> Temporarily Abandoned      Reminder: _____									
Comment: <div>Last Production - March 2023</div>									
Corrective Action: <div></div> Date: _____									

### Reclamation - Storm Water - Pit

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Berms						
Ditches						
		Ditches				
				Material Handling And Spill Prevention		
Check Dams						

Comment: Stormwater BMPs need implementation and maintenance. Insufficient BMPs to control vehicle tracking.

Corrective Action: Provide proper Stormwater BMPs to control runoff in a manner that minimizes erosion, transport of sediment offsite, and site degradation. Vehicle tracking BMPs to control potential sediment discharges from operational roads, well pads, and other unpaved surfaces.

Date: 06/07/2023

Pits: ☒ NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
702501782	Inspection Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6237777">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6237777</a>