

Comment: Empty containers and miscellaneous parts within methanol tank containment. See Photo #2.



Photo from INC showing empty containers within containment.

Corrective actions taken—Removed empty container and other trash from within the containment.



Comment: 2 unmarked guy anchors. See Photo #3.

Corrective Action: Install proper guy line markers per Rule 1003.a or remove if non-serviceable or not needed for ongoing operations. Date: 09/04/2023



Picture from INC showing unmarked guy line anchor.

Corrective action taken—Installed new guy line anchor marker.



Comment: Berm walls constructed of plastic liner, chicken wire, and washed gravel. Berm walls in need of repair. See Photos #4 & #5.

Corrective Action: Repair or install berms or other secondary containment devices per Rule 912.d.(1). Date: 09/10/2023



Pictures from INC of the berm walls in need of repair.

Corrective action taken—Rebuilt/Repaired the berm wall.



