

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

08/29/2023

Submitted Date:

08/30/2023

Document Number:

702501781

**FIELD INSPECTION FORM**

Loc ID: 316241      Inspector Name: Burchett, Kirby      On-Site Inspection:       2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 10775  
 Name of Operator: KT RESOURCES LLC  
 Address: 3381 WESTBROOK LANE  
 City: HIGHLANDS      State: CO      Zip: 80129

**Findings:**

- 13 Number of Comments
- 4 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Gale, Tony	(303) 886-8733	tony@kt-res.com	
Adams, Karen	(303) 886-8733	adams@kt-res.com	
Baumgras, Dan	(307) 321-3299	Dan@KT-Res.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
259422	WELL	SI	04/01/2023	GW	103-10092	WRD WYATT 36-14	SI

**General Comment:**

[ECMC Inspection Report Summary](#)

On Tuesday, 8/29/2023, Inspector Kirby Burchett, conducted a follow up field inspection at KT Resources LLC on the WRD Wyatt 36-14 well, Location #316241, in Rio Blanco County, Colorado. This location is within or in close proximity to a Parks and Wildlife (CPW) District with High Priority, NSO, Density, and Other Consultation Habitat regulations.

Any Corrective Actions from previous Inspections are still applicable.

Follow up inspection to verify compliance issues observed during Inspections #702501018 on 3/21/23 and #702501279 on 5/9/23 have been resolved. No action has been taken to resolve Stormwater BMP issues. Due date will remain 6/7/23.

While there during normal production operations the following compliance issues were observed:

1. Weeds.
  2. Stained soil at tank battery.
  3. Ground stains below tank burner.
  4. Gas meter calibration card not in compliance.
  5. Stormwater BMPs have not been implemented or maintained.
- Refer to Inspection Photos for observed compliance issues.

A follow up on this site inspection will be conducted to ensure all compliance issues have been corrected to comply with ECMC rules.

**Location**

Overall Good:

<b>Signs/Marker:</b>			
Type	CONTAINERS		
Comment:	Chemical tank on containment		
Corrective Action:			Date:
Type	BATTERY		
Comment:			
Corrective Action:			Date:
Type	OTHER		
Comment:	As Location Entrance signs are replaced: The Well name; The Commission's Location identification number (ID #); The Operator's telephone number where it may be reached at all times; and the Telephone number(s) for local emergency services (911 where available) will be required.		
Corrective Action:			Date:
Type	WELLHEAD		
Comment:	As Wellhead signs are replaced: The Well name; The API Number; and Its legal location, including the quarter/quarter section will be required.		
Corrective Action:			Date:
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:			Date:

Emergency Contact Number:			
Comment:	<input type="text" value="(800) 288-0560 or 911"/>		
Corrective Action:	<input type="text"/>		Date: _____

<b>Good Housekeeping:</b>			
Type	WEEDS		
Comment:	Oil and Gas Locations will be kept free of all Undesirable Plant Species.		
Corrective Action:	Maintain noxious weed control on all disturbed and reclaimed areas as a result of Oil & Gas activities including access roads.		Date: <u>09/06/2023</u>

Overall Good:

<b>Spills:</b>			
Type	Area	Volume	
PW/CO	Tank	<= 1 bbl	
Comment:	Soil staining at loadout valve and tank burner		
Corrective Action:	Remove and properly dispose of oily waste and impacted soil.		Date: <u>09/14/2023</u>

In Containment: Yes

Comment:

Multiple Spills and Releases?

<b>Equipment:</b>			corrective date
Type: Gas Meter Run	# 1		

Comment:	Gas meter calibration displayed but out of compliance.				
Corrective Action:	Meters will be calibrated annually unless more frequent calibration is required by contractual obligations.			Date:	09/09/2023
Type:	Bird Protectors	# 2			
Comment:					
Corrective Action:				Date:	
Type:	Bradenhead	# 1			
Comment:					
Corrective Action:				Date:	
Type:	Horizontal Heater Treater	# 1			
Comment:					
Corrective Action:				Date:	
Type:	Ancillary equipment	# 1			
Comment:	Chemical tank on containment				
Corrective Action:				Date:	
Type:	Deadman # & Marked	# 4			
Comment:					
Corrective Action:				Date:	
Type:	Plunger Lift	# 1			
Comment:					
Corrective Action:				Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	300 BBLS	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Other	Adequate			
Comment:	Unlined metal and earth.			
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	1	300 BBLS	HEATED STEEL AST		,
Comment:					

Corrective Action:	Date:
--------------------	-------

**Paint**

Condition	Adequate		
Other (Content)			
Other (Capacity)			
Other (Type)			

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Other	Adequate				
Comment: <span style="color:blue;">Unlined metal and earth.</span>					
Corrective Action:					Date:

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:			Date:

**Flaring:**

Type			
Comment:			
Corrective Action:			Date:

**Inspected Facilities**

Facility ID: 259422 Type: WELL API Number: 103-10092 Status: SI Insp. Status: SI

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: \_\_\_\_\_

Comment:

Corrective Action:  Date: \_\_\_\_\_

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Berms						
		Ditches				
				Material Handling And Spill Prevention		
Check Dams						
Ditches						

Comment: Stormwater BMPs need implementation and maintenance. Insufficient BMPs to control vehicle tracking.

Corrective Action: Provide proper Stormwater BMPs to control runoff in a manner that minimizes erosion, transport of sediment offsite, and site degradation. Vehicle tracking BMPs to control potential sediment discharges from operational roads, well pads, and other unpaved surfaces.

Date: 06/07/2023

Pits:  NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403516540	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6237800">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6237800</a>
702501782	Inspection Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6237777">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6237777</a>