

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYLand Office Denver
Lease No. D-033804(b)
Unit _____RECEIVED
OCT - 1 1970

SUNDRY NOTICES AND REPORTS ON WELLS

SOLO. OIL & GAS CONS. COMM.

NOTICE OF INTENTION TO DRILL.....	SUBSEQUENT REPORT OF WATER SHUT-OFF.....
NOTICE OF INTENTION TO CHANGE PLANS.....	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....	SUBSEQUENT REPORT OF ALTERING CASING.....
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR.....
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....	SUBSEQUENT REPORT OF ABANDONMENT.....
NOTICE OF INTENTION TO PULL OR ALTER CASING.....	SUPPLEMENTARY WELL HISTORY.....
NOTICE OF INTENTION TO ABANDON WELL.....	

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

October 9, 1956

Well No. 18a is located 1500 ft. from [N] line and 1200 ft. from [E] line of sec. 11NW 1 SW 1 Sec. 11 IN 100 6th P.
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)
Rangely (Field) Rio Blanco Colorado
(County or Subdivision) (State or Territory)The elevation of the derrick floor above sea level is 5339 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

To pull rods and tubing to clean out mud.
Well mudded off, rods stuck.

Approved as a matter of record.

DVR	
FJP	
HHM	
JAM	✓
JJD	

Approved 3-10-58

G. G. Frazier
District Engineer

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company LuBauer Petroleum Co. (McKinzie operation)Address 739 E McKinleyPhoenix, ArizonaBy LuBauerTitle Owner