

State of Colorado
Energy & Carbon Management Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

403502855

Date Received:

09/06/2023

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

3 of 3 CAs from the FIR responded to on this Form

3 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 77330

Name of Operator: SG INTERESTS I LTD

Address: 100 WAUGH DR SUITE 400

City: HOUSTON State: TX Zip: 77007

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

Interests_SG

inspection@sginterests.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 708300782

Inspection Date: 08/14/2023

FIR Submit Date: 08/16/2023

FIR Status: _____

Inspected Operator Information:

Company Name: SG INTERESTS I LTD

Company Number: 77330

Address: 100 WAUGH DR SUITE 400

City: HOUSTON State: TX Zip: 77007

LOCATION - Location ID: 324469

Location Name: FEDERAL 11-90-24-611S90W Number: 24NWSE County: GUNNISON

Qtrqtr: NWSE Sec: 24 Twp: 11S Range: 90W Meridian: 6

Latitude: 39.085589 Longitude: -107.393622

FACILITY - API Number: 05-051-00 Facility ID: 271432

Facility Name: FEDERAL 11-90-24 Number: 1

Qtrqtr: NWSE Sec: 24 Twp: 11S Range: 90W Meridian: 6

Latitude: 39.085589 Longitude: -107.393622

CORRECTIVE ACTIONS:

1 ☒ CA# 178711

Corrective Action: Install appropriate fittings to allow bradenhead visual inspection as per Rule 419.a.(1), (2)

Date: 08/26/2023

Response: CA COMPLETED

Date of Completion: 08/24/2023

Operator Comment: SG field staff confirmed on 8/24 the BH valve was visible and open. on 8/31/23 a cellar was installed over the buried BH valve. During the install, the buried valve was excavated/exposed, confirmed open, cellar installed and backfilled with gravel. Please see attached photo documentation.

COGCC Decision: Approved pending re-inspection

COGCC
Representative:

2 ☒ CA# 178712

Corrective Action: Remove unused supplies equipment to comply with Rule 606.

Date: 08/31/2023

Response: CA COMPLETED

Date of Completion: 08/17/2023

Operator Comment: Fan shroud stored near pump jack was removed on 8/17/23. Please see attached photo documentation.

COGCC Decision: Approved pending re-inspection

COGCC
Representative:

3 ☒ CA# 178713

Corrective Action: Oil and gas operators shall implement and maintain Best Management Practices (BMPs) at all oil and gas locations to comply with Rule 1002.

Date: 08/31/2023

Response: CA COMPLETED

Date of Completion: 08/30/2023

Operator Comment: SG has attached a map showing the access route to the Federal 11-90-24 1 well pad. The photos that were taken along the access road to the south are not related to this location. It took SG longer than 7 days to pinpoint where these photos were taken, therefore we were unable to submit a factual review request. Photo#05877 is south of SG's field and along a lease road that is operated and used solely by Gunnison Energy. SG does not use this route to access our field. Photo#0576 is taken on a lease road that is not used to access the Federal 11-90-24 1, however, it is used to access the Eck 12-90-1 location that is operated by SG. Due to the nature of the sluffing on the section of the road, SG has contacted a Contractor who is in the process of getting a bid together for the work. SG anticipates to have this sluffing repaired in the next few weeks. Please see the attached map depicting the access route to the Federal 11-90-24 1 and the approximate location of the photos related to the corrective action.

COGCC Decision: Approved pending re-inspection

COGCC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Tracy Arnett

Signed:

Title: Reg Permitting

Date: 9/6/2023 12:24:36 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

Document Number	Description
403502855	FIR RESOLUTION SUBMITTED
403521432	Photo Documentation
403521435	Map of Access Route to Location

Total Attach: 3 Files