

Inspection Photos

9/6/2023

Operator: TEP ROCKY MOUNTAIN LLC -
96850

Location Number: 335678
Rio Blanco County, CO

Aaron Trujillo
NW Reclamation Specialist
CECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC - 96850

Location Number: 335678



Photo 1: Photos 1-2 taken from the north end of the working pad surface. Photos provide an overview of the Location from east, southeast, southwest to west



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC - 96850

Location Number: 335678



Photo 2: See comments under photo 1.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC - 96850

Location Number: 335678



September 6, 2023



September 6, 2023

Photo 3: Photos example showing reclamation in process.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC - 96850

Location Number: 335678



September 6, 2023

Photo 4: Unused equipment improperly stored within the secondary containment BMP.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC - 96850

Location Number: 335678




Photo 5: Signage missing at well.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC - 96850

Location Number: 335678



Photo 6: Photo example showing control measures to stabilize the cut slopes, as well as to minimize erosion and degradation are missing or insufficient.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC - 96850

Location Number: 335678



Photo 7: Erosion degradation on cut slopes.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC - 96850

Location Number: 335678



Photo 8: Photo taken from the north end of the Location, adjacent to the sediment trap. Stormwater runoff is not being diverted in to trap, resulting in erosion occurring on the slope.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC - 96850

Location Number: 335678



September 6, 2023

Photo 9: Photo example showing erosion degradation along access road



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources