

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

09/14/2023

Submitted Date:

09/15/2023

Document Number:

710500007

FIELD INSPECTION FORMLoc ID 484357 Inspector Name: Sanchez, Chris On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 10797

Name of Operator: DESERT EAGLE OPERATING LLC

Address: 17101 PRESTON RD SUITE 105

City: DALLAS State: TX Zip: 75248

Status Summary:☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

13 Number of Comments

5 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Beardslee, Tom		tom.beardslee@state.co.us	ECMC
Sanchez, Chris		chris.sanchez@state.co.us	ECMC
Costa, Ryan		ryan.costa@state.co.us	ECMC
Bulf, Cathy		cathybulf@gmail.com	Desert Eagle Operating llc
Butler, Brad	972-345-9195	butleroil@yahoo.com	Desert Eagle Operating llc

General Comment:

This is an Environmental Inspection for the Red Rocks 1-14, API # 05-071-09928; Location # 484674, active drilling location located in Las Animas County, Co

CA's From Reclamation inspection # 713600215 still apply.

Comply with Reclamation Inspection CA's and Dates.

Location

Lease Road:			
Type	Access		
comment:	Lease road was wet and rutted from vehicle traffic during time of inspection.		
Corrective Action:	Maintain vehicle tracking BMP's on the oil and gas location to comply with rule 1002.f. (2)F. Comply with rule 1002 f	Date:	10/12/2023

Overall Good: ☐**Emergency Contact Number:**

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type			
Comment:	Location had 5 gallon buckets knocked over on location		
Corrective Action:	Self-inspection, maintenance and good housekeeping procedures and schedules. Per Rule 1002.f.2.D	Date:	09/26/2023

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

Type	PIT		
Comment:	Lined Trench/Pit on location has steep sidewalls and no protection to protect animals, public health, safety and welfare		
Corrective Action:	Rule 913.b(5)B.i. Operators will fence or cover open excavations to prevent access when sites are not attended.	Date:	09/19/2023

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Location Construction

Location ID: 484674 CDP: _____

Comment: _____

Corrective Action: _____

Date: 09/08/2023

Form 2A COAs:

Comment: _____

Corrective Action: _____

Date: _____

Wildlife BMPs:

Comment: _____

Corrective Action: _____

Date: _____

Comment: CA's From Reclamation inspection # 713600215 apply

Corrective Action: Comply with Reclamation Inspection CA's and Dates

Date: _____

On Site Inspection (305):

Surface Owner Contact Information:

Name: _____

Address: _____

Phone Number: _____

Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____

Phone Number: _____

Date Onsite Request Received: _____

Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:

Summary of Operator Response to Landowner Issues:

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

Environmental**Spills/Releases:**Type of Spill: DRILLING FLUIDS

Estimated Spill Volume: _____

Comment: Pit liner for location compromised on the NW corner of the pit/trench; ECMC noted there was a release of water from the pit/trench, which flowed behind the liner. On 9/15/2023, ECMC spoke with Brad Butler, Owner Operator for Desert Eagle Operating llc.

Corrective Action: Repair and maintain best management practices to control and contain all spills/releases of E&P waste to protect the environment, public health, safety, welfare and the environment. Operator shall submit an Initial form 19 for the location within 24 hours to notify the ECMC of the release. Immediately initiate cleanup efforts

Date: 09/16/2023Reportable: YESGPS: Lat 37.465340Long -103.526290

Proximity to Surface Water: _____

Depth to Ground Water: _____

Water Well Complaint:

Lat

Long

DWR Receipt Num: _____

Owner Name: _____

GPS : _____

Field Parameters:

Sample Location: _____

Comment: _____

COGCC Comments

Comment	User	Date
Fuel tank on location does not have legible placards, noted a small stain under filter/hose for fueling, cleanup and contain potential spills form fuel tank per Rule 1002.f.(2)F.	sanchezcc	09/15/2023
Observed Oily water flowing South off Rig Mat to native soils, Reference Picture # 6. Operator shall use best efforts to maintain oily runoff from affecting native soils per Rule 1002.f.(2)F.	sanchezcc	09/15/2023

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
710500009	Inspection Photos 710500007	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6253048