

FORM  
INSPRev  
X/20

# State of Colorado

## Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

08/31/2023

Submitted Date:

08/31/2023

Document Number:

713300068

### FIELD INSPECTION FORM

Loc ID 318308 Inspector Name: Kester, Michael On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Operator Information:**

OGCC Operator Number: 46290  
Name of Operator: KP KAUFFMAN COMPANY INC  
Address: 1700 LINCOLN ST STE 4550  
City: DENVER State: CO Zip: 80203

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION  
 FOLLOW UP INSPECTION REQUIRED  
 NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

- 10 Number of Comments  
4 Number of Corrective Actions  
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
, KPK		cogcc@kpk.com	<a href="#">All inspections</a>
Silver, Randy		randy.silver@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
241086	WELL	SI	05/01/2021	GW	123-08874	SUCKLA-BROWN UNIT 13	SI

**General Comment:**

**Location**

<b>Lease Road:</b>			
Type	Access		
comment:	overgrown vegetation		
Corrective Action	Comply with rule 606	Date:	09/14/2023

Overall Good:

<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:	good		
Corrective Action:		Date:	

<b>Emergency Contact Number:</b>			
Comment:			
Corrective Action:		Date:	

<b>Good Housekeeping:</b>			
Type	WEEDS		
Comment:	Overgrown vegetation		
Corrective Action:	Comply with rule 606	Date:	09/14/2023

Type	UNUSED EQUIPMENT		
Comment:	Concrete support pad for pumping unit		
Corrective Action:	Comply with Rule 606	Date:	10/02/2023

Overall Good:

<b>Spills:</b>			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			

<b>Equipment:</b>			corrective date
Type: Ancillary equipment	# 1		
Comment:	Electrical panel		
Corrective Action:		Date:	
Type: Other	# 1		
Comment:	Concrete puming unit support pad		
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:			
Corrective Action:		Date:	

<b>Venting:</b>			
Yes/No	NO		
Comment:			

Corrective Action:		Date:	
--------------------	--	-------	--

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

**Inspected Facilities**

Facility ID: 241086 Type: WELL API Number: 123-08874 Status: SI Insp. Status: SI

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: \_\_\_\_\_

Comment: Well is overdue for Mechanical Integrity Test. MIT requires 10-day notification via Form 42. Well plugging requires an approved Form 6 Intent to Abandon to Plug Well. Last production date was 4-1-21.

Corrective Action: Produce well after performing successful mechanical integrity test per Rule 417 or plug well. To maintain shut-in status, the well must be able to demonstrate ability to produce without mechanical intervention. Date: 10/07/2023

**BradenHead**

Date of Last Brhd Test: 08/22/2022 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: \_\_\_\_\_

End Surf Csg Pressure: 0

Comment: Report needs to be submitted

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**COGCC Comments**

Comment	User	Date
<p>ECMC Inspection Report Summary                      On Thursday 8-31-2023 at approximately 08:30, I, Inspector Michael Kester, conducted an on-site inspection.                      Location: Suckla Brown Unit 13                      Operator: KPK                      API#: 123-08874                      County: Weld                      While there, I observed well that appeared to be shut in.                      During this inspection the following possible compliance issues were observed:                      MIT required, Rule 417, corrective action date 10-7-2023.                      Weeds, Rule 606, corrective action date 10-2-2023 See attached photo #1, 2, 3, &amp; 4.                      Unused equipment, Rule 606, corrective action date 10-2-2023 See attached photo 2 &amp; 3.                      Weather conditions: Dry and sunny.                      A follow up on this site inspection needs to be conducted to ensure the Compliance issues have been corrected to comply with ECMC rules.                      This is a summary of inspection report.</p> <p>This inspection does not nullify any orders or NOAV from the COGCC</p>	kesterm	08/31/2023

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403526124	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6247301">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6247301</a>
713300069	site pic	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6247255">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6247255</a>