

Storm Water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC PA 332-33 Pad
Location ID: 335392



**Location Overview: Location is within High
Priority/Density/Black Bear Habitat areas. Location is within
Rule 411a Surface Water External Buffer.**

Section/Township/Range: 33 6S95W

Storm water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC PA 332-33 Pad
Location ID: 335392



North West corner of location.



North East corner of location.



South West corner of location.



South East corner of location.

Storm water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC PA 332-33 Pad
Location ID: 335392



Photo # 9709 Erosion & transport of sediment off location/insufficient BMP's



Photo # 9712 Erosion & transport of sediment off location/insufficient BMP's

Storm water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC PA 332-33 Pad
Location ID: 335392



Photo # 9713 Erosion & transport of sediment off location/insufficient BMP's



Photo # 9714 Erosion & transport of sediment off location/insufficient BMP's

Storm water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC PA 332-33 Pad
Location ID: 335392



Photo # 9715 Erosion & transport of sediment off location/insufficient BMP's



Photo # 9716 Erosion & transport of sediment off location/insufficient BMP's

Storm water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC PA 332-33 Pad
Location ID: 335392



Photo # 9724 Erosion & transport of sediment off location/insufficient BMP's



Photo # 9725 Erosion & transport of sediment off location/insufficient BMP's

Storm water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC PA 332-33 Pad
Location ID: 335392



Photo # 9726 Erosion & transport of sediment off location/insufficient BMP's

Photo # 9728 Erosion & transport of sediment off location/insufficient BMP's

Storm water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC PA 332-33 Pad
Location ID: 335392



Photo # 9733 Erosion & transport of sediment off location/insufficient BMP's



Photo # 9734 Erosion & transport of sediment off location/insufficient BMP's

Storm water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC PA 332-33 Pad
Location ID: 335392



Photo # 9735 Erosion & transport of sediment off location/insufficient BMP's