

OG  
RE  
CONSERVATION COMMISSION  
STATE OF COLORADO



99999999

for Patented and Federal lands.  
for State lands.

**SUNDRY NOTICES AND REPORTS ON WELLS**

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☐ GAS WELL ☒ OTHER ☐

2. NAME OF OPERATOR  
**Alfred M. Buranek**

3. ADDRESS OF OPERATOR  
**525 Atlas Building, Salt Lake City, Utah 84101**

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.  
See also space 17 below.)  
At surface **Well 1, Denver 056445-A, SW1/4 SW1/4 Sec. 1, T. 2 N.,  
At proposed prod. zone R. 3 W., Ute Meridian, Mack Field, Mesa Co.,  
Colorado**

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)  
**RTD**

5. LEASE DESIGNATION AND SERIAL NO.

**Denver 056445-A**

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

**Knapp Sundown**

8. FARM OR LEASE NAME

9. WELL NO.

**Number 1, Gov.**

10. FIELD AND POOL, OR WILDCAT

**Mack (510), Morrison**

11. SEC., T., R., M., OR BLK. AND  
SURVEY OR AREA

**Sec. 1, T. 2 N., R. 3 W., Ute  
M.**

12. COUNTY OR PARISH

**Mesa**

13. STATE

**Colorado**

16. **Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data**

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

PULL OR ALTER CASING

FRACTURE TREAT

MULTIPLE COMPLETE

SHOOT OR ACIDIZE

ABANDON

REPAIR WELL

CHANGE PLANS

(Other)

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

REPAIRING WELL

FRACTURE TREATMENT

ALTERING CASING

SHOOTING OR ACIDIZING

ABANDONMENT

(Other)

(NOTE: Report results of multiple completion on Well  
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

Patterson Well Service and Salvage Co., of Grand Junction, Colorado has been retained to properly plug and abandon said well. Work on the well will commence before November 22, 1969. The following procedure has been outlined by Mr. Patterson:

1. Kill the well with heavy mud.
2. Place a twenty (20) sack plug across the productive zone and the perforations back into the seven inch (7") casing. (Elevation is approximately 2200 feet RTD)
3. Locate the free point across the seven inch (7") casing and recover any recoverable casing.
4. Place a 100' plug half way in and half way out of the seven inch (7") stub.
5. Place a ten (10) sack plug across the bottom of the surface casing.
6. Place a five (5) sack plug in the top of the hole and erect a dry hole marker.
7. Clean up the well location

DVR	
FJP	✓
HHM	✓
JAM	✓
JJD	



00603336

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE

DATE **November 14, 1969**

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

DIRECTOR

CO. & CONS. COMM.

NOV 25 1969

John Rossey - Western Slope  
Gas Co.  
244-6300

<u>1965</u>	<u>MCF</u>
Jan.	999
Feb.	1083
Mar.	1119
Apr.	1330
May	1122
June	1274
July	1306
Aug.	1133

Bogdanich - D 056445A  
Mack Creek Field  
Mesa County

Nov.	1130
Dec.	1172