



99999999

103-08842

Date 9-24-83

Send For:

Form 4

Form 5

Cmt. Verif.

Form 10

Logs

Plat

Other

Requested by: J.K.



00053446

Bill

STATE OF COLORADO
OIL AND GAS CONSERVATION COMMISSION

DEPARTMENT OF NATURAL RESOURCES
SUITE 380 LOGAN TOWER BUILDING
1580 LOGAN STREET

DENVER, COLORADO 80203

WILLIAM R. SMITH
Director

(303) 866-3531

RICHARD D. LAMM
Governor

FRANK J. PIRO
Deputy Director

March 27, 1985

Diamond Back Drilling and Supply
P.O. Box 96
Rangely, Colorado 81648

RE: Well Reports - Rangely Field

Gentlemen:

Although we have had some response to previous requests there are still a number of your wells for which the file is incomplete.

The wells and needed information is as follows:

1. Expired Permit - Need Status:

Emerald 119	26-2N-103W
Emerald 236	6-1N-102W
Emerald 237	1-1N-103W
Emerald 238	36-2N-103W
Emerald 239	1-1N-103W
Emerald 241	25-2N-103S
Emerald 242	30-2N-102W
Emerald 244	25-2N-103W
Emerald 261	26-2N-103W
Emerald 281	26-2N-103W
Emerald 283	25-2N-103W
Emerald 285	26-2N-103W
Emerald 286	25-2N-103W
Emerald 288	36-2N-103W
Emerald 289	36-2N-103W
Emerald 80-1-4	36-2N-103W
Anderson 17-4	17-2N-103W
Anderson 80-1-1	17-2N-103W
Federal 80-1-2	21-2N-103W
Harrison Smith 80-1-8	10-1N-102W
Emerald 278	36-2N-103W (Intent to Abandon Filed)

*5-8-86
Status
Q. K.*

2. Need Completion Report - OGCC Form 5 and Plugging Report,
(if abandoned):

Emerald 245	30-2N-102W
Emerald 247	31-2N-102W
Emerald 248	31-2N-102W
Emerald 249	31-2N-102W
Emerald 250	31-2N-102W
Emerald 251	30-2N-102W
Emerald 252	30-2N-102W
Emerald 253	31-2N-102W
Emerald 254	31-2N-102W
Emerald 255	36-2N-102W
Emerald 256	25-2N-102W
Emerald 260	25-2N-103W
Emerald 262	36-2N-103W
Emerald 263	36-2N-103W
Emerald 268	36-2N-103W
Emerald 269	36-2N-103W
Emerald 270	36-2N-103W
Emerald 274	36-2N-103W
Emerald 276	36-2N-103W
Emerald 277	36-2N-103W
Emerald 280	36-2N-103W
Emerald 80-1-12 (217)	36-2N-103W

3. No Certificate of Clearance or Authorization to Transport
Oil or Gas Off of the Lease - OGCC Form 10:

Government J-1	10-1N-102W
Emerald 230	36-2N-103W
Emerald 232	25-2N-103W

4. Survey Plat:

Emerald 187	36-2N-103W
Emerald 188	26-2N-103W
Emerald 190	31-2N-103W
Emerald 191	36-2N-103W
Emerald 192	36-2N-103W
Emerald 193	36-2N-103W
Emerald 194	36-2N-103W
Emerald 195	36-2N-103W
Emerald 196	26-2N-103W
Emerald 197	25-2N-103W
Emerald 198	25-2N-103W
Emerald 199	36-2N-103W
Emerald 200	36-2N-103W
Emerald 201	36-2N-103W
Emerald 202	36-2N-103W

Emerald 203	36-2N-103W
Emerald 204	36-2N-103W
Emerald 222	36-2N-103W
Emerald 223	36-2N-103W

5. Subsequent Reports of Abandonment - OGCC Form 5:

Emerald 224	25-2N-103W
Emerald 229	36-2N-103W
Emerald 231	36-2N-103W
Emerald 234	36-2N-103W
Emerald 235	36-2N-103W

From Mizel letter dated March 13, 1985 - Plat

With the volume of work that passes thru this office, receipt of some information is sometimes misplaced; however, it is imperative we have copies of previously submitted reports.

If the above information is not submitted by May 1, 1985, or a reasonable explanation furnished on specific wells, I intend to take this matter before the Commission at the hearing set for June 15, 1985 for consideration of such as they may deem appropriate.

If you have any questions, please contact Patricia Beaver at 866-3531.

Very truly yours,

William R. Smith

William R. Smith, P.E.
Director

WRS:bm

cc: Jim Kenney

STATE OF COLORADO
OIL AND GAS CONSERVATION COMMISSION

DEPARTMENT OF NATURAL RESOURCES
ROOM 721, CENTENNIAL BUILDING
1313 SHERMAN STREET
DENVER, COLORADO 80203

WILLIAM R. SMITH
Director

FRANK J. PIRO
Deputy Director

(303) 866-3531

January 31, 1985

RICHARD D. LAMM
Governor

Diamond Back Drilling & Supply Co.
PO Box 96
Rangely, CO 81648

RE: Failure to comply with State Regulations

Dear Sirs:

Recent inquiries into Diamond Back's interests in the Rangely Field indicate a serious problem. Diamond Back has a record of failing to comply with Colorado's regulations by not filing information reports. We wish to bring this to your prompt attention and respectfully request you redress the following problems.

The following wells have an intent to abandon (Form 4) filed without subsequent reports of abandonment, cement verifications, completion reports, or electric logs: (If electric logs were not run on a well, please so state on (form 5) completion report.)

Emerald	274	36-2N-103W
	276	36-2N-103W
	277	36-2N-103W
	278	36-2N-103W

The following wells have been plugged and abandoned without filing a completion report (Form 5) or electric logs:

Emerald	260	25-2N-103W
	262	36-2N-103W
	263	36-2N-103W
	268	36-2N-103W
	269	36-2N-103W
	270	36-2N-103W

The following wells have exceeded the expiration date on their permit to drill without subsequent notice of status: (If these wells have not been drilled a (Form 4) sundry notice of location abandonment must be filed.)

Emerald	236	6-1N-102W
	237	1-1N-103W
	239	1-1N-103W
	244	25-2N-103W

Emerald	255	36-2N-102W
	261	26-2N-103W
	280	36-2N-103W
	281	26-2N-103W
	283	25-2N-103W
Federal	80-1-2	21-2N-103W
Anderson	80-2-2	17-2N-103W
Harrison Smith	80-1-8	10-1N-102W

The state realizes that some of our requirements are not clearly stated and are often misunderstood. If there are any questions regarding proper filing of forms please contact us. We will gladly assist in completing necessary forms.

The state wishes to give Diamond Back this opportunity to correct these problems without resorting to penalties.

Thank you for your cooperation in this matter.

Respectfully,

James Kenney
Petroleum Engineer

JK:jw