

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

09/25/2023

Submitted Date:

09/25/2023

Document Number:

707901109**FIELD INSPECTION FORM**Loc ID 319889 Inspector Name: Silver, Randy On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 46290Name of Operator: KP KAUFFMAN COMPANY INCAddress: 1700 LINCOLN ST STE 4550City: DENVER State: CO Zip: 80203**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:2 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
201791	WELL	PR	12/01/2022	OW	001-07195	NORTH YORK 1	PR

General Comment:

Inspected Facilities

Facility ID: 201791 Type: WELL API Number: 001-07195 Status: PR Insp. Status: PR

Complaint

Comment:

Inspection in response to complaint.
 Field Inspector Assigned: Randy Silver
 Complaint Received
 Date: 9-25-2023
 Complaint Contacted: Yes via phone left voice mail
 Date: 9-21-2023 Time: 10:30AM
 Location ID # 319889 and 320504
 Location name: North York #1 and Cundall #6-12
 Inspection Document # 707901107 and 713300112
 Complaint inspection document # 707901112
 Complaint Document form 18 # 40334477
 Nature of Complaint: Noise
 Field Inspector Actions:
 On 9-21-2023, I Randy Silver area field inspector was assigned a complaint received by COGCC staff in reference to Noise. The complainant Ryan Bone 15757 Josephine Circle east Thornton CO stated the issues were occurring outside of complainants home. On 9-21-2023, I attempted to make contact with the complainant who indicated that on 9-19-2023 experiencing a loud backfiring noise coming from an oil and gas location. I performed a complete site inspection of the oil and gas location and associated wells in the area. At time of inspection, I found a PU motor on the North York #1 that has an extension on the existing muffler on PU gas powered motor. Noise does not appear to be out of compliance but operator can eliminate disruption to the public by pointing muffler extension toward the HWY instead of subdivision.
 Weather conditions: Clear and dry
 No violation of COGCC rules were observed at the time of the inspection.
 All information has been reviewed and site inspection information has been submitted to the ECMC for further review.

Corrective Action:

Date:

COGCC Comments

Comment

User

Date

See inspection doc#'s 707901107 and 713300112 for full inspection.

silverr

09/25/2023