

State of Colorado Energy & Carbon Management Commission



1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Document Number:
403542998

Date Received:
09/27/2023

FIR RESOLUTION FORM

Overall Status:

CA Summary:

1 of 1 CAs from the FIR responded to on this Form

1 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10758
Name of Operator: OGRIS OPERATING LLC
Address: PO BOX 53467
City: MIDLAND State: TX Zip: 79710

Contact Name and Telephone:
Name: _____
Phone: () _____ Fax: () _____
Email: _____

Additional Operator Contact:

Contact Name	Phone	Email
<u>WARD, GIENA</u>	<u>719-220-4041</u>	<u>gward@ogrisop.com</u>
<u>BACA, DAVE</u>	<u>719-859-4066</u>	<u>dbaca@ogrisop.com</u>

COGCC INSPECTION SUMMARY:

FIR Document Number: 695108675
Inspection Date: 09/25/2023 FIR Submit Date: 09/25/2023 FIR Status: _____

Inspected Operator Information:

Company Name: OGRIS OPERATING LLC Company Number: 10758
Address: PO BOX 53467
City: MIDLAND State: TX Zip: 79710

LOCATION - Location ID: 309436

Location Name: HILL RANCH-634S67W Number: 36NESW County: LAS ANIMAS
Qtrqtr: NESW Sec: 36 Twp: 34S Range: 67W Meridian: 6
Latitude: 37.037729 Longitude: -104.839785

FACILITY - API Number: 05-071- -00 Facility ID: 295025

Facility Name: HILL RANCH Number: 36-11
Qtrqtr: NESW Sec: 36 Twp: 34S Range: 67W Meridian: 6
Latitude: 37.037729 Longitude: -104.839785

CORRECTIVE ACTIONS:

1 CA# 182075

Corrective Action: Conduct maintenance on equipment, cleanup stained material and review self inspection processes. COMPLY WITH RULE 1002,(2).D. Date: 09/30/2023

Response: CA COMPLETED Date of Completion: 09/26/2023

Operator Comment: Photo 1: THE HYDRAULIC LEAK WAS REPAIRED AND EQUIPMENT MAINTENANCE HAS BEEN PERFORMED. ALL IMPACTED SOIL WAS REMOVED FROM THE LOCATION AND FRESH PAD MATERIAL ADDED AROUND THE WELLHEAD. THE SELF INSPECTION PROCESS HAS BEEN REVIEWED.

NOTE: THE INSPECTION REPORTS THIS CORRECTIVE ACTION TO BE AT HILL RANCH 36-11 BUT UPON INVESTIGATION, THE LEAKING HYDRAULIC HOSES AND SOIL STAINS (AS SHOWN IN INITIAL INSPECTION REPORT PHOTOS) WERE DISCOVERED AT HILL RANCH 36-10-67.

COGCC Decision: _____

COGCC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment: CORRECTIVE ACTION COMPLETED, SEE PHOTO LOG FOR DETAILS.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: GIENA ZECHES

Signed: _____

Title: ENVIRONMENTAL

Date: 9/27/2023 10:06:35 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

Document Number **Description**

403543002	PHOTO LOG
-----------	-----------

Total Attach: 1 Files