



COLORADO OIL & GAS CONSERVATION COMMISSION FIELD INSPECTION FORM

<input checked="" type="checkbox"/> NOTICE OF UNSATISFACTORY INSPECTION	1120 Lincoln Street, Suite 801 Denver, CO 80203 (303)894-2100
<input type="checkbox"/> NOTICE OF SATISFACTORY INSPECTION	

API No. 05- <u>107 - 60445206</u>	LEASE NAME: <u>Mackinley #1</u>				
LOCATION: <u>S55E, 23, 6N, 87W</u>	OPERATOR: <u>Bannon Martin Greer</u>				
DATE: <u>6-20-95</u>	INSPECTOR: <u>Adkins</u>				
Insp. Type: <u>10</u>	Insp. Status: <u>45</u>	PA: Y <input type="checkbox"/> N <input checked="" type="checkbox"/>	Pass/Fail: P <input checked="" type="checkbox"/> F <input type="checkbox"/>	Viol.: Y <input checked="" type="checkbox"/> N <input type="checkbox"/>	NOV: Y <input checked="" type="checkbox"/> N <input type="checkbox"/>

INSPECTION ITEM	COMMENTS	INPUT
Well ID Signs	<u>NONE</u>	
Pits (Reserve/Production)	<u>none</u>	
Fences	<u>none</u>	
Tank Battery Equipment	<u>Tank 1/2 W in saddle 1-250, RP unit 7/8" rods, 2 3/4 Tbg, Tank, 6 drums</u>	
Fire Walls/Berms/Dikes	<u>N/A</u>	
General Housekeeping	<u>poor</u>	
Spills (Oil/Water)	<u>Production + op. Workover fluids allowed to drain to pond below site</u>	
Bradenhead		
Drilling Well/Workover		
Surface Rehabilitation		
Miscellaneous		

CORRECTIVE ACTION REQUIRED: Clear up debris, remove junk from location

Date Corrective Action Required By: 9-1-95 **Date Remedied:**

This report is a Notice of Inspection. The Commission requires that you correct any deficiencies shown on this report in a timely manner. Failure to comply may result in enforcement action by the Commission.