

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

09/28/2023

Submitted Date:

10/03/2023

Document Number:

713600268

FIELD INSPECTION FORM

Loc ID 309300 Inspector Name: COSTA, RYAN On-Site Inspection 2A Doc Num: _____

Operator Information:

OGCC Operator Number: 10758
Name of Operator: OGRIS OPERATING LLC
Address: PO BOX 53467
City: MIDLAND State: TX Zip: 79710

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Findings:

- 2 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
WARD, GIENA		gward@ogrisop.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
309300	LOCATION	AC			-	NEW ELK-633S68W 25NENE	RI

General Comment:

On 9/28/2023, Ryan Costa conducted a location and stormwater management inspection. See attached photos and additional details within this report.

Location

Lease Road:

Type Access

comment:

Corrective ActionL

Date:

Overall Good:

Signs/Marker:

Type WELLHEAD

Comment:

Corrective Action:

Date:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good:

Spills:

Type	Area	Volume			

In Containment: No

Comment:

Multiple Spills and Releases?

Venting:

Yes/No

Comment:

Corrective Action:

Date:

Flaring:

Type

Comment:

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: There is an erosion channel along the main access road ascending the hillside to the location. There appears to be degraded plastic snadbags placed into the erosion channel that need to be replaced with and more effective BMP. There is also an erosion channel near the location. Corrective action will remain out of compliance until completed.

Corrective Action: Install or repair required BMPs per Rule 1002.f.(2)

Date: 09/28/2023

Pits: NO SURFACE INDICATION OF PIT

Permit:	Facility ID	Permit Num	Expiration Date
	293737	2059540	
	293737	2059540	

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
713600269	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6271692