

FORM  
INSPRev  
X/20State of Colorado  
Oil and Gas Conservation Commission1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/05/2023

Submitted Date:

10/05/2023

Document Number:

699107502

## FIELD INSPECTION FORM

 Loc ID 327613 Inspector Name: Burns, Adam On-Site Inspection  2A Doc Num: \_\_\_\_\_
**Operator Information:**OGCC Operator Number: 46290Name of Operator: KP KAUFFMAN COMPANY INCAddress: 1700 LINCOLN ST STE 4550City: DENVER State: CO Zip: 80203**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Findings:**9 Number of Comments3 Number of Corrective Actions

- 
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Watzman, Ross	303-825-4822	rwatzman@kpk.com	
,		cogcc@kpk.com	<a href="#">All Inspections</a>
Tibbs, Dan	970-539-0664	Dtibbs@kpk.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
247130	WELL	PR	12/01/2022	OW	123-14927	SEYFRIED 2	SI

**General Comment:**[Routine Inspection](#)

**Location**

Overall Good:

**Signs/Marker:**

Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:	Adequate	Date:	
Corrective Action:			

**Good Housekeeping:**

Type	UNUSED EQUIPMENT		
Comment:	Unused Equipment next to the pumping unit needs to be removed for good housekeeping. See attached photo		
Corrective Action:	Comply with Rule 606.	Date:	10/20/2023
Type	WEEDS		
Comment:	Overgrown Vegetation grown throughout the location, need to be removed for good housekeeping. See attached photos		
Corrective Action:	Comply with Rule 606.	Date:	10/20/2023

Overall Good:

**Spills:**

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
OTHER	0	500 BBLS	LVST		40.253200,-104.279100
Comment:	Crude/ water				
Corrective Action:				Date:	

**Paint**

Condition	<input type="text"/>
Other (Content)	<input type="text"/>
Other (Capacity)	<input type="text"/>
Other (Type)	<input type="text"/>

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
	Inadequate	Walls Insufficient			
Comment:	Horizontal 500 BBL tank on location needs a secondary containment. See attached photos				
Corrective Action:	Install berms or other secondary containment devices per Rule 603.o.			Date:	10/20/2023

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type			
Comment:			
Corrective Action:		Date:	

**Inspected Facilities**

Facility ID: 247130 Type: WELL API Number: 123-14927 Status: PR Insp. Status: SI

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: \_\_\_\_\_

Comment:

Corrective Action:  Date: \_\_\_\_\_

**BradenHead**

Date of Last Brhd Test: 03/21/2023 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: \_\_\_\_\_

End Surf Csg Pressure: 0

Comment:

Corrective Action:  Date: \_\_\_\_\_

**COGCC Comments**

Comment	User	Date
<p><a href="#">ECMC Inspection Report Summary</a>                      On Tuesday 10/3/23 at approximately 0938hrs I, Inspector Adam Burns, Conducted an on-site inspection at Seyfried 2 of KP Kauffman Company INC. API #05-123-14927 in Weld County, Colorado.                      During this inspection the following possible compliance issues were observed:                      Overgrown Vegetation grown throughout the location, need to be removed for good housekeeping. Comply with Rule 606. With a Corrective Action date of 10/20/23                      Unused Equipment next to the pumping unit needs to be removed for good housekeeping. Comply with Rule 606. With a Corrective Action date of 10/20/23                      Horizontal 500 BBL tank on location needs a secondary containment. Install berms or other secondary containment devices per Rule 603.o. With a Corrective Action date of 10/20/23                      A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with ECMC rules.                      This is a summary of the inspection report.</p>	burnsa	10/05/2023

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699107503	Inspection Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6275473">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6275473</a>