

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

09/26/2023

Submitted Date:

10/05/2023

Document Number:

694100173

FIELD INSPECTION FORM

Loc ID 329083 Inspector Name: Robinson, Taylor On-Site Inspection 2A Doc Num: _____

Operator Information:

OGCC Operator Number: 100322
Name of Operator: NOBLE ENERGY INC
Address: 2001 16TH STREET SUITE 900
City: DENVER State: CO Zip: 80202

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Findings:

- 6 Number of Comments
- 2 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
,		rbucogccinspectionreports@chevron.onmicrosoft.com	
,		rbucogccinspectionreports@chevron.onmicrosoft.com	All Inspections
,		rbucogccinspectionreports@chevron.onmicrosoft.com	All Inspections

General Comment:

This is an environmental inspection for Location ID 329083 Atreyu, Reed, and Fanny pad. Any corrective actions from previous inspections that have not been addressed are still applicable. There were no operator or contract environmental personnel on location at the time of this field inspection. Photos attached to document site conditions.

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type

Comment: trash, oily waste on site. Statewide unnecessary equipment, weeds, waste, and trash requirements

Corrective Action: Comply with Rule 606

Date: 10/19/2023

Overall Good:

Spills:

Type

Area

Volume

In Containment: No

Comment:

Multiple Spills and Releases?

Venting:

Yes/No

Comment:

Corrective Action:

Date:

Flaring:

Type

Comment:

Corrective Action:

Date:

Location Construction

Location ID: 329083 CDP: _____

Comment: _____

Corrective Action: _____

Date: _____

Form 2A COAs:

Comment: _____

Corrective Action: _____

Date: _____

Wildlife BMPs:

Comment: _____

Corrective Action: _____

Date: _____

Comment: Washout occurring. Slight discharge of sediment offsite on east side of pad.

Corrective Action: Regrade pad in areas of washout/rutting. Pull back any sediment that has left the pad location. Stormwater management Erosion Control. Install or repair required BMPs per Rule 1002.f.(2)C

Date: 10/12/2023

On Site Inspection (305):

Surface Owner Contact Information:

Name: _____

Address: _____

Phone Number: _____

Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____

Phone Number: _____

Date Onsite Request Received: _____

Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____

Phone Number: _____

Agreed to Attend: _____

Summary of Landowner Issues:

Summary of Operator Response to Landowner Issues:

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

Environmental

Spills/Releases:

Type of Spill: _____ Estimated Spill Volume: _____

Comment:

Corrective Action: Date: _____

Reportable: _____ GPS: Lat _____ Long _____

Proximity to Surface Water: _____ Depth to Ground Water: _____

Water Well Complaint:

DWR Receipt Num: _____ Owner Name: _____ GPS : _____ Lat _____ Long _____

Field Parameters:

Sample Location: _____ Comment: _____

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
694100174	photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6275567