

FORM
INSPRev
X/20

State of Colorado Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

10/02/2023

Submitted Date:

10/02/2023

Document Number:

702501921

FIELD INSPECTION FORM

Loc ID 314686 Inspector Name: Burchett, Kirby On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 12930
 Name of Operator: CALCO DBA CALLISTER CO
 Address: 1230 W 1400 N
 City: LEHI State: UT Zip: 84043

Findings:

- 5 Number of Comments
1 Number of Corrective Actions
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
Callister, Jan	(801) 487-4721	jec-apex@outlook.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
229262	WELL	TA	06/01/2021	GW	103-06357	CALLISTER- GOVERNMENT 3	TA

General Comment:[ECMC Inspection Report Summary](#)

On Monday, 10/02/2023, Inspector Kirby Burchett, conducted a follow up field inspection at CALCO dba Callister Co. on the Callister-Government 3 well, Location #314686, in Rio Blanco County, Colorado.
 This location is within or in close proximity to a CPW District with High Priority, NSO, and Density Habitat Regulations.

Any Corrective Actions from previous Inspections are still applicable.

Follow up inspection in response to compliance issues observed during Inspection #702501675 on 7/12/23. Well has since been plugged. Waiting to cut off wellhead and verify cement tops.

A follow up on this site inspection will be conducted to ensure all compliance issues have been corrected to comply with ECMC rules.

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date:

Overall Good:

Spills:					
Type	Area	Volume			

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:				corrective date
Type: Deadman # & Marked	# 4			
Comment:				
Corrective Action:				Date:
Type: Other	# 1			
Comment: Wellhead				
Corrective Action:				Date:

Venting:			
Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:			
Type			
Comment:			
Corrective Action:			Date:

Inspected Facilities

Facility ID: 229262 Type: WELL API Number: 103-06357 Status: TA Insp. Status: TA

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment: Well has been plugged. 5 day minimum waiting period before cutting off wellhead

Corrective Action: Submit 42 - Notice of Operations 48 hours before cutting off wellhead. Compliance Inspector may verify cement tops before installing marker.

Date: 10/03/2023

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: [Operator is responsible for maintaining Best Management Practices \(BMPs\) to control vehicle tracking and potential sediment discharges from operational roads, well pads, and other unpaved surfaces.](#)

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403547879	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6271221