

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/05/2023

Submitted Date:

10/09/2023

Document Number:

713600282

FIELD INSPECTION FORMLoc ID 324843 Inspector Name: COSTA, RYAN On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 16520

Name of Operator: CHEMCO INC

Address: 6970 SOUTH HOLLY CIR STE 206

City: CENTENNIAL State: CO Zip: 80112

Status Summary:

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

4 Number of Comments

3 Number of Corrective Actions

- ☒
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Neher, Morgan		morgan@chemco-og.com	
Enforcement		dnr_cogccenforcement@state.co.us	
Neher, Gray		gh.neher@chemco-og.com	
Sanchez, Chris		chris.sanchez@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
213091	WELL	SI	08/02/2022	OW	061-06452	BAUGHMAN 6	RI

General Comment:

On 10/5/2023, Ryan Costa conducted a follow up of the previous inspection #713600280.
The corrective actions of the previous reclamation inspection have not been performed.
Operator is directed to perform corrective actions outlined on this inspection report immediately.
Non-compliance with the Rules will be referred to enforcement.
See attached photos and additional details within this report.

LocationOverall Good: ☐

Signs/Marker:			
Type	WELLHEAD		
Comment:	The well sign is laying on the ground not properly installed. Corrective action will remain out of compliance until completed.		
Corrective Action:	Install sign to comply with Rule 605.d.	Date:	10/05/2023

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type	STORAGE OF SUPL		
Comment:	Some of the unused supplies were removed however, there are still parts laying next to the pumpjack. There is also an unused pipe riser near the tank. Corrective action will remain out of compliance until completed.		
Corrective Action:	Comply with Rule 606.	Date:	08/09/2023

Overall Good: ☐

Spills:				
Type	Area	Volume		
Crude Oil				
Comment:	There is oil stained soils at the pumpjack, tank battery, and separator that must be cleaned up and properly disposed. It appears dirt was spread over the impacted areas since previous inspection and impacted soils were not cleaned up. Upon further investigation with ENV staff the spill appears to be reportable under 912.b. Corrective action will remain out of compliance until completed.			
Corrective Action:	Control and contain spills/releases and clean up per Rule 912.a. Submit Form 19 within 72 hours to report the spill of impacted material and Contact ECMC EPS staff per Rule 912.b.			Date: 08/09/2023

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
713600283	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6278036