

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

09/28/2023

Submitted Date:

10/03/2023

Document Number:

713600268

**FIELD INSPECTION FORM**Loc ID 309300 Inspector Name: COSTA, RYAN On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

OGCC Operator Number: 10758

Name of Operator: OGRIS OPERATING LLC

Address: PO BOX 53467

City: MIDLAND State: TX Zip: 79710

**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

2 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
WARD, GIENA		gward@ogrisop.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
309300	LOCATION	AC			-	NEW ELK-633S68W 25NENE	RI

**General Comment:**

On 9/28/2023, Ryan Costa conducted a location and stormwater management inspection.  
See attached photos and additional details within this report.

**Location****Lease Road:**

Type	Access		
comment:			
Corrective Action:		Date:	

Overall Good: ☒**Signs/Marker:**

Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

**Emergency Contact Number:**

Comment:		
Corrective Action:		Date: _____

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Comment:		<p>There is an erosion channel along the main access road ascending the hillside to the location. There appears to be degraded plastic snadbags placed into the erosion channel that need to be replaced with and more effective BMP. There is also an erosion channel near the location. Corrective action will remain out of compliance until completed.</p>				
Corrective Action:		<p>Install or repair required BMPs per Rule 1002.f.(2)</p>				Date: 09/28/2023
<b>Pits:</b> <input type="checkbox"/> NO SURFACE INDICATION OF PIT						

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403548312	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6271737">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6271737</a>
713600269	Inspection Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6271692">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6271692</a>