

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/05/2023

Submitted Date:

10/10/2023

Document Number:

713600288

FIELD INSPECTION FORMLoc ID 324836 Inspector Name: COSTA, RYAN On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 16520

Name of Operator: CHEMCO INC

Address: 6970 SOUTH HOLLY CIR STE 206

City: CENTENNIAL State: CO Zip: 80112

Status Summary:

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

6 Number of Comments

5 Number of Corrective Actions

- ☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Neher, Morgan		morgan@chemco-og.com	
Welsh, Brian		brian.welsh@state.co.us	
Sanchez, Chris		chris.sanchez@state.co.us	
Neher, Gray		gh.neher@chemco-og.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
213031	WELL	PR	11/01/2022	OW	061-06392	BAUGHMAN 7	RI

General Comment:

On 10/5/2023, Ryan Costa conducted a follow up of the previous inspection #713600090.
The corrective actions of the previous reclamation inspection have not been performed.
Operator is directed to perform corrective actions outlined on this inspection report immediately.
See attached photos and additional details within this report.

Location

Lease Road:			
Type	Access		
comment:	Vehicles have driven outside of the access road boundary creating rutting and disturbance which needs to be repaired. The access road needs to be stabilized per Rule 1002.f.		
Corrective Action:	Vehicle must stay on original access road boundary per Rule 1002.e.	Date:	10/05/2023

Overall Good: ☐

Signs/Marker:			
Type	TANK LABELS/PLACARDS		
Comment:	Tank labels are faded. Corrective action will remain out of compliance until completed.		
Corrective Action:	Install sign to comply with Rule 605.h.	Date:	10/05/2023

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good: ☐

Spills:				
Type	Area	Volume		
Crude Oil	Pump Jack			
Comment:	There was a leak at the wellhead and at the separator. There is oil stained soils that must be cleaned up. Covering up the stained soil as previously observed may result in enforcement referral. Operator must clean up and properly dispose E&P waste.			
Corrective Action:	Immediately Control and contain spills/releases and clean up per Rule 912.a.			Date: 10/05/2023

In Containment: No

Comment:

☐ Multiple Spills and Releases?

Fencing/:			
Type	PUMP JACK		
Comment:	The fencing at the pumpjack is incomplete to prevent livestock entry. Corrective action will remain out of compliance until completed.		
Corrective Action:	Comply with the fencing requirements per the 1002a rules	Date:	10/05/2023

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: There are oil stained soils at the base of the pumpjack that have not been cleaned up. It appears dirt was spread over the stained soils to cover up and hide the spill. Covering up the stained soil may result in enforcement referral. Operator must clean up and properly dispose Non - E&P waste.
Previous corrective action was not completed.
There is vehicle rutting of the access road which is not stabilized. BMP's such as gravel must be installed to allow access during wet conditions.

Corrective Action: Conduct maintenance on equipment, cleanup stained material and review self inspection processes. Install or repair required BMPs per Rule 1002.f.(2)C

Date: 05/31/2023

Pits: ☒ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
713600289	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6279039