

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/09/2023

Submitted Date:

10/10/2023

Document Number:

699107542**FIELD INSPECTION FORM**

Loc ID      Inspector Name:      On-Site Inspection ☐  
 331757      Burns, Adam      2A Doc Num: \_\_\_\_\_

**Operator Information:**OGCC Operator Number: 65110Name of Operator: O'BRIEN ENERGY RESOURCES CORPAddress: 18 CONGRESS ST STE 207City: PORTSMOUTH      State: NH      Zip: 03801**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION  
☒ FOLLOW UP INSPECTION REQUIRED  
☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**9 Number of Comments6 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Forma, Joseph	603-427-2099 x111	joeforma@obenergy.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
331757	LOCATION	AC			-	NORTH LOST CREEK- 63N62W 20SWNE	SI

**General Comment:**[Tank Battery Inspection.](#)[This is a follow up to prior inspection document number #699107162. CA's were not corrected.](#)

**Location**Overall Good: ☐**Signs/Marker:**

Type	TANK LABELS/PLACARDS		
Comment:	Missing NFPA placard for the pit. See attached photo		
Corrective Action:	Install sign to comply with Rule 605.h.	Date:	09/22/2023
Type	TANK LABELS/PLACARDS		
Comment:	Missing pit capacity label. See attached photo		
Corrective Action:	Install sign to comply with Rule 605.h.	Date:	09/22/2023
Type	BATTERY		
Comment:	Missing Battery sign. See attached photos		
Corrective Action:	Install sign to comply with Rule 605.a.	Date:	09/22/2023

**Emergency Contact Number:**

Comment:		
Corrective Action:		Date: _____

**Good Housekeeping:**

Type	WEEDS		
Comment:	Overgrown vegetation around the tank battery needs to be removed for good housekeeping. See attached photos		
Corrective Action:	Comply with Rule 606	Date:	09/22/2023

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Equipment:**

Type: Other	#		corrective date
Comment:	Unmarked risers need marked. See attached photo		
Corrective Action:	Upon removing a flowline or crude oil transfer line from use with the intent to abandon, an operator must immediately apply OOSLAT to the risers. OOSLAT must stay in place at all times during the process of abandoning the flowline or crude oil transfer line until the operator removes the riser. Comply with Rule 1105.b	Date:	09/22/2023

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type			
Comment:			
Corrective Action:		Date:	

**Inspected Facilities**Facility ID: 331757 Type: LOCATION API Number: - Status: AC Insp. Status: SI**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned

Reminder: \_\_\_\_\_

Comment: SI Tank Battery  
No FIRR was submitted.Corrective Action: When a Field Inspection Report includes a corrective action, upon completion of that corrective action the Operator will submit to the Director a Field Inspection Report Resolution Form ("FIRR"). Per rule 210.b.Date: 10/12/2023**COGCC Comments**

Comment	User	Date
<p>ECMC Inspection Report Summary</p> <p>On Monday 10/9/23 at approximately 0907hrs I, Inspector Adam Burns, Conducted an on-site inspection to prior inspection document #699107162 at North Lost Creek-63N62W 20SWNE Tank Battery of O'Brien Energy Resources Corp. Location ID #331757 in Weld County, Colorado.</p> <p>During this inspection the following possible compliance issues were observed:</p> <p>Missing pit capacity label. Install sign to comply with Rule 605.h. With a Corrective Action date of 9/22/23</p> <p>Missing NFPA placard for the pit. Install sign to comply with Rule 605.h. With a Corrective Action date of 9/22/23</p> <p>Missing Battery sign. Install sign to comply with Rule 605.a. With a Corrective Action date of 9/22/23</p> <p>Overgrown vegetation around the tank battery needs to be removed for good housekeeping. Comply with Rule 606. With a Corrective Action date of 9/22/23</p> <p>Unmarked risers need marked. Upon removing a flowline or crude oil transfer line from use with the intent to abandon, an operator must immediately apply OOSLAT to the risers. OOSLAT must stay in place at all times during the process of abandoning the flowline or crude oil transfer line until the operator removes the riser. Comply with Rule 1105.b. With a Corrective Action date of 9/22/23</p> <p>No FIRR was submitted. When a Field Inspection Report includes a corrective action, upon completion of that corrective action the Operator will submit to the Director a Field Inspection Report Resolution Form ("FIRR"). Per rule 210.b. With a Corrective Action date of 10/12/23</p> <p>No CA's were corrected</p> <p>A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with ECMC rules.</p> <p>This is a summary of the inspection report.</p>	burnsa	10/10/2023

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699107543	Inspection Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6279696">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6279696</a>