

**FORM
INSP**Rev
X/20

State of Colorado

Oil and Gas Conservation Commission

 1120 Lincoln Street, Suite 801, Denver, Colorado 80203
 Phone: (303) 894-2100 Fax: (303) 894-2109


Inspection Date:

10/09/2023

Submitted Date:

10/11/2023

Document Number:

699107544

FIELD INSPECTION FORM
 Loc ID 331279 Inspector Name: Burns, Adam On-Site Inspection ☐ 2A Doc Num:
Operator Information:

OGCC Operator Number: 65110

Name of Operator: O'BRIEN ENERGY RESOURCES CORP

Address: 18 CONGRESS ST STE 207

City: PORTSMOUTH State: NH Zip: 03801

Status Summary:

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

8 Number of Comments

4 Number of Corrective Actions

☒ Corrective Action Response Requested
**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**
Contact Information:

Contact Name	Phone	Email	Comment
Forma, Joseph	603-427-2099 x111	joeforma@obenergy.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
260833	WELL	TA	07/30/2020	GW	123-20424	LOST CREEK O'BRIEN 3-20	TA

General Comment:

This is a follow up to prior inspection document #699107158. CA's were not corrected.

LocationOverall Good: ☒

Signs/Marker:			
Type	WELLHEAD		
Comment:	well need to be fixed in the near future.		
Corrective Action:		Date:	

Emergency Contact Number:			
Comment:			
Corrective Action:			Date: _____

Good Housekeeping:			
Type	WEEDS		
Comment:	Overgrown vegetation around the well needs to be removed for good housekeeping. See attached photos.		
Corrective Action:	Comply with Rule 606.	Date:	09/22/2023

Overall Good: ☐

Spills:			
Type	Area	Volume	

In Containment: No

Comment: ☐ Multiple Spills and Releases?

Fencing/:			
Type	WELLHEAD		
Comment:	Panel Fence needs to be fixed. See attached photo		
Corrective Action:	Comply with the fencing requirements per the 1002a rules.	Date:	09/22/2023

Venting:			
Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:			
Type			
Comment:			
Corrective Action:		Date:	

Inspected FacilitiesFacility ID: 260833 Type: WELL API Number: 123-20424 Status: TA Insp. Status: TA**Idle Well**Purpose: ☐ Shut In ☒ Temporarily Abandoned Reminder: _____Comment: T/A
No FIRR was submitted.Corrective Action: When a Field Inspection Report includes a corrective action, upon completion of that corrective action the Operator will submit to the Director a Field Inspection Report Resolution Form ("FIRR"). Per rule 210.b.Date: 10/13/2023**BradenHead**Date of Last Brhd Test: 11/27/2021 Annual Brhd Completed? NoLast Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: NONEEnd Surf Csg Pressure: 0Comment: No updated annual BH test on file. Submit reports. Form 17 #403257019 indicates it was last tested on 12/8/20.09/22/2023Corrective Action: Submit reports as per Rule 419.

Date: _____

COGCC Comments

Comment	User	Date
<p>ECMC Inspection Report Summary</p> <p>On Monday 10/9/23 at approximately 0913hrs I, Inspector Adam Burns, Conducted an on-site inspection to prior inspection document #699107158 at Lost Creek O'Brien 3-20 of O'Brien Energy Resources Corp. API #05-123-20424 in Weld County, Colorado.</p> <p>During this inspection the following possible compliance issues were observed:</p> <p>Overgrown vegetation around the well needs to be removed for good housekeeping. Comply with Rule 606. With a Corrective Action date of 9/22/23</p> <p>Panel Fence needs to be fixed. Comply with the fencing requirements per the 1002a rules. With a Corrective Action date of 9/22/23</p> <p>No updated annual BH test on file. Submit reports. Form 17 #403257019 indicates it was last tested on 12/8/20. Submit reports as per Rule 419. With a Corrective Action date of 9/22/23</p> <p>No FIRR was submitted. When a Field Inspection Report includes a corrective action, upon completion of that corrective action the Operator will submit to the Director a Field Inspection Report Resolution Form ("FIRR"). Per rule 210.b. With a Corrective Action date of 10/13/23</p> <p>No CA's were corrected</p> <p>A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with ECMC rules.</p> <p>This is a summary of the inspection report.</p>	burnsa	10/11/2023

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699107545	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6281129