

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/09/2023

Submitted Date:

10/11/2023

Document Number:

699107546

**FIELD INSPECTION FORM**Loc ID 331882 Inspector Name: Burns, Adam On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

OGCC Operator Number: 65110

Name of Operator: O'BRIEN ENERGY RESOURCES CORP

Address: 18 CONGRESS ST STE 207

City: PORTSMOUTH State: NH Zip: 03801

**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

5 Number of Comments

2 Number of Corrective Actions

- ☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Forma, Joseph	603-427-2099 x111	joeforma@obenergy.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
267813	WELL	PR	03/01/2022	GW	123-21441	LOST CREEK 5	SI

**General Comment:**

This is a follow up to prior inspection document #69910154. 1 out of 2 CA were not corrected.

**Location**Overall Good: ☐

Emergency Contact Number:

Comment: Corrective Action: Date: Overall Good: ☐**Spills:**

Type	Area	Volume			

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

**Inspected Facilities**Facility ID: 267813 Type: WELL API Number: 123-21441 Status: PR Insp. Status: SI**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned

Reminder: \_\_\_\_\_

Comment: No FIRR was submitted.Corrective Action: When a Field Inspection Report includes a corrective action, upon completion of that corrective action the Operator will submit to the Director a Field Inspection Report Resolution Form ("FIRR"). Per rule 210.b.Date: 10/13/2023**BradenHead**Date of Last Brhd Test: 12/01/2021Annual Brhd Completed? NoLast Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: NONEEnd Surf Csg Pressure: 0Comment: No updated annual BH test on file. Submit reports. Form 17 #403257040 indicates it was last tested on 12/8/20.

09/22/2023

Corrective Action: Submit reports as per Rule 419.

Date: \_\_\_\_\_

**COGCC Comments**

Comment

User

Date

ECMC Inspection Report Summary  
 On Monday 10/9/23 at approximately 0917hrs I, Inspector Adam Burns,  
 Conducted an on-site inspection to prior inspection document #699107154 at Lost Creek 5  
 of O'Brien Energy Resources Corp.  
 API #05-123-21441 in Weld County, Colorado.  
 During this inspection the following possible compliance issues were observed:  
 No updated annual BH test on file. Submit reports. Form 17 #403257040 indicates it was  
 last tested on 12/8/20. Submit reports as per Rule 419. With a Corrective Action date of  
 9/22/23  
 No FIRR was submitted. When a Field Inspection Report includes a corrective action, upon  
 completion of that corrective action the Operator will submit to the Director a Field  
 Inspection Report Resolution Form ("FIRR"). Per rule 210.b. With a Corrective Action date  
 of 10/13/23  
 1 out of 2 CA's were corrected  
 A follow up on this site inspection needs to be conducted to ensure the  
 compliance issues have been corrected to comply with ECMC rules.  
 This is a summary of the inspection report.

burnsa

10/11/2023

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/webblink/>) and search by document number:

Document Num	Description	URL
699107547	Inspection Photo	<a href="http://ogccwebblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6281130">http://ogccwebblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6281130</a>