

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

10/11/2023

Submitted Date:

10/11/2023

Document Number:

708901927

FIELD INSPECTION FORM

Loc ID 324111 Inspector Name: Smelser, Wayne On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 96850
Name of Operator: TEP ROCKY MOUNTAIN LLC
Address: 1058 COUNTY ROAD 215
City: PARACHUTE State: CO Zip: 81635

Findings:

6 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
, TEP		COGCCInspectionReports@terraep.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
457251	Domestic Tap	AC	09/11/2018		-	Domestic Tap 4SWSW	AC

General Comment:

[CECMC Inspection Report Summary](#)
On 10/11/2023 at approximately 12:56 hours, I, Compliance Specialist, Wayne Smelser Conducted an on-site inspection at TEP ROCKY MOUNTAIN LLC Domestic Tap 4SWSW Location # 324111 in Garfield County Colorado.
While there, I observed the domestic tap is derived from TEP sales line.
This is a summary of inspection report

Location				
Lease Road:				
	Type Access			
	comment:			
	Corrective ActionL			Date:
Overall Good: <input type="checkbox"/>				
Emergency Contact Number:				
	Comment:	<input style="width: 80%;" type="text"/>		
	Corrective Action:	<input style="width: 80%;" type="text"/>		
Date: _____				
Overall Good: <input type="checkbox"/>				
Spills:				
Type	Area	Volume		
In Containment: No				
	Comment:	<input style="width: 80%;" type="text"/>		
<input type="checkbox"/> Multiple Spills and Releases?				
Fencing/:				
	Type OTHER			
	Comment:	Hog panels around domestic tap		
	Corrective Action:			Date:
Equipment:				
Type: Other		# 1		corrective date
	Comment:	Domestic tap		
	Corrective Action:			Date:
Venting:				
	Yes/No NO			
	Comment:			
	Corrective Action:			Date:
Flaring:				
Type				
	Comment:			
	Corrective Action:			Date:

Inspected Facilities

Facility ID: 457251 Type: Domestic Tap API Number: - Status: AC Insp. Status: AC

Producing Well

Comment: While there, I observed the domestic tap is derived from TEP sales line. The pressure is regulated by a big Joe regulator, following the regulator there is a fluid knock out. All fittings appear to be adequately sized to handle the maximum operating pressure of the regulator.

No PRV or odorizer observed

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment:

Corrective Action:

Date:

Pits: NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
Domestic tap inspection only	smelserw	10/11/2023

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
708901928	Inspection 708901927 photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6281792