

Storm Water Management and Erosion control
Location Name: TEP Rocky Mountain LLC COOK RMV 77-33 Pad
Location # 323946



**Location Overview: Location is within High
Priority/Density/Black Bear Habitat areas.**
Section/Township/Range: 33 6S94W

Storm water Management and Erosion control
Location Name: TEP Rocky Mountain LLC COOK RMV 77-33 Pad
Location # 323946



North West corner of location.



North East corner of location.



South West corner of location.



South East corner of location.

Storm water Management and Erosion control
Location Name: TEP Rocky Mountain LLC COOK RMV 77-33 Pad
Location # 323946



Photo # 2740 Lack of stabilization/compaction

Photo # 2741 Lack of stabilization/compaction

Storm water Management and Erosion control
Location Name: TEP Rocky Mountain LLC COOK RMV 77-33 Pad
Location # 323946



Photo # 2742 Lack of stabilization/compaction

Photo # 2743 Lack of stabilization/compaction

Storm water Management and Erosion control
Location Name: TEP Rocky Mountain LLC COOK RMV 77-33 Pad
Location # 323946



Photo # 2744 Lack of stabilization/compaction



Photo # 2745 Lack of stabilization/compaction

Storm water Management and Erosion control
Location Name: TEP Rocky Mountain LLC COOK RMV 77-33 Pad
Location # 323946



Photo # 2746 Lack of stabilization/compaction